

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8009290346 DOC. DATE: 80/09/19 NOTARIZED: NO DOCKET #  
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438  
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439  
 AUTH. NAME AUTHOR AFFILIATION  
 MILLS, L.M. Tennessee Valley Authority  
 RECIP. NAME RECIPIENT AFFILIATION  
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

MA/1

SUBJECT: First interim deficiency re deficient fillet welds. Program being implemented to reinspect & correct all deficient welds. Next rept due by 801215.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR L ENCL 0 SIZE: L  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	L	ENCL		ID	CODE/NAME	L	ENCL
ACTION:	A/D	LICENSNG 04	1		YOUNGBLOOD, B	05	1		
	RUSHBROOK, M.	06	1		BOURNIA, T.	07	1		
INTERNAL:	AD/RCI/IE	17	1		AEOD	18	1		
	ASLBP/J. HARD		1		D/DIR HUM FAC15		1		
	EDO & STAFF	19	1		EQUIP QUAL BR11		1		
	HYD/GEO BR	22	1		I&E	09	2		
	LIC QUAL BR	12	1		MPA	20	1		
	NRC PDR	02	1		OELD	21	1		
	PROC/TST REV	13	1		GA BR	14	1		
<u>REG FILE</u>	01	1		RUTHERFORD, W. IE		1			
STANDRDS DEV	21	1							
EXTERNAL:	ACRS	16	16	1	LPDR	03	1		
	NSIC	08	1						

SEP 30 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 40 ENCL 0

R

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 19, 1980

Mr. James R. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - QA BREAKDOWN - DEFICIENT FILLET  
WELDS - NCR'S 1188 AND 1203 - FIRST INTERIM REPORT

On May 7, 1980, R. W. Wright, NRC-OIE Region II, was informed that non-conformance (NCR) 1188 was determined to be reportable in accordance with 10 CFR 50.55(e). Since that time, related NCR 1203 has been determined to be reportable in accordance with 10 CFR 50.55(e). This was followed by our first interim report dated June 6, 1980.

TVA is implementing a program to reinspect fillet welds and correct all deficiencies which are identified. We expect to submit our next report by December 15, 1980.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

B019  
S  
1/0

8009290346

An Equal Opportunity Employer

S