

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8009290346 DOC.DATE: 80/09/19 NOTARIZED: NO DOCKET #
 FACIL:50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH.NAME AUTHOR AFFILIATION
 MILLS,L.M. Tennessee Valley Authority
 RECIP.NAME RECIPIENT AFFILIATION
 O'REILLY,J.P. Region 2, Atlanta, Office of the Director

MA/1

SUBJECT: First interim deficiency re deficient fillet welds, Program
 being implemented to reinspect & correct all deficient
 welds. Next rept due by 801215.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	A/D LICENSNG 04	1	YOUNGBLOOD, B 05	1
	RUSHBROOK, M. 06	1	BOURNIA, T. 07	1
INTERNAL:	AD/RCI/IE 17	1	AEOD 18	1
	ASLBP/J. HARD	1	D/DIR HUM FAC15	1
	EDO & STAFF 19	1	EQUIP QUAL BR11	1
	HYD/GEO BR 22	1	I&E 09	2
	LIC QUAL BR 12	1	MPA 20	1
	NRC PDR 02	1	OELD 21	1
	PROC/IST REV 13	1	QA BR 14	1
	<u>REG FILE</u> 01	1	RUTHERFORD, W. IE	1
	STANDRDS DEV 21	1		
EXTERNAL:	ACRS 16	16	LPDR 03	1
	NSIC 08	1		

SEP 30 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 40 ENCL 0

R

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 19, 1980

Mr. James R. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - QA BREAKDOWN - DEFICIENT FILLET
WELDS - NCR'S 1188 AND 1203 - FIRST INTERIM REPORT

On May 7, 1980, R. W. Wright, NRC-OIE Region II, was informed that non-conformance (NCR) 1188 was determined to be reportable in accordance with 10 CFR 50.55(e). Since that time, related NCR 1203 has been determined to be reportable in accordance with 10 CFR 50.55(e). This was followed by our first interim report dated June 6, 1980.

TVA is implementing a program to reinspect fillet welds and correct all deficiencies which are identified. We expect to submit our next report by December 15, 1980.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

3019
S
11/0

8009290346

An Equal Opportunity Employer

S