

# REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8103040700 DOC. DATE: 81/02/23 NOTARIZED: NO DOCKET #  
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438  
 AUTH. NAME: AUTHOR AFFILIATION  
 MILLS, L.M. Tennessee Valley Authority  
 RECIP. NAME: RECIPIENT AFFILIATION  
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Responds to 800428 ltr re INRYCO tendon installation operations & related QA/QC activities. Inspectors to be maintained on simultaneously stressed groups of dome & horizontal tendons. INRYCO resumed tendon associated work.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Construction Deficiency Report (10CFR50.55E)

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	A/D LICENSNG 04	1 1	YOUNGBLOOD, B 05	1 1
	RUSHBROOK, M. 06	1 1	BOURNIA, T. 07	1 1
INTERNAL:	AD/RCI/IE 17	1 1	ASLBP/J. HARD	1 1
	D/DIR HUM FAC 15	1 1	DIR, DIV OF LIC	1 1
	EDO & STAFF 19	1 1	EQUIP QUAL BR 11	1 1
	HYD/GEO BR 22	1 1	I&E 09	1 1
	LIC QUAL BR 12	1 1	MPA 20	1 1
	NRC PDR 02	1 1	OELD 21	1 1
	PROC/TST REV 13	1 1	QA BR 14	1 1
	REG FILE 01	1 1	RUTHERFORD, W. IE	1 1
	STANDARDS DEV 21	1 1		
EXTERNAL:	ACRS 16	16 16	LPDR 03	1 1
	NSIC 08	1 1		

MAR 05 1981


TOTAL NUMBER OF COPIES REQUIRED: LTR 39 ENCL 0

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

February 23, 1981



Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNIT 1 - CONFIRMATION OF ACTION

This is in response to your letter dated April 24, 1980, RII:JPO 50-438 concerning INRYCO's tendon installation operations and related QA/QC activities for Bellefonte Nuclear Plant unit 1.

This letter confirms the telephone conversation on February 6, 1981, between W. R. Dahnke of TVA and J. J. Lenahan of your staff. As indicated in the telephone conference, TVA will maintain a minimum of two TVA inspectors and two INRYCO QC inspectors on each group of three dome tendons stressed simultaneously, and a minimum of one TVA inspector and one INRYCO QC inspector in each group of two horizontal tendons stressed simultaneously.

As discussed with you on February 6, 1981, and in accordance with your confirmation of concurrence letter dated February 10, 1981, TVA has allowed INRYCO to resume work associated with stressing of horizontal and dome tendons. This completes the items outlined in your April 24, 1980, letter.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

3019  
S  
1/0

8103040700

An Equal Opportunity Employer