

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

MA/1

ACCESSION NBR: 8006250227 DOC. DATE: 80/06/20 NOTARIZED: NO DOCKET #
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH. NAME AUTHOR AFFILIATION
 MILLS, L.M. Tennessee Valley Authority
 RECIP. NAME RECIPIENT AFFILIATION
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards second revised final deficiency report re blown fuses in low voltage switchgear.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
ACTION:	AD A/D LICENSING 21	1	1	BC YOUNGBLOOD, B. 15	1	1
	LA RUSHBROOK, M. 20	1	1	PM BOURNIA, T. 14	1	1
INTERNAL:	AD/RCI/IE	1	1	AEOD	1	1
	EDO & STAFF 07	1	1	EQUIP QUAL BR 16	1	1
	FIELD COOR/IE 13	1	1	HANAUER, S.	1	1
	HYD/GEO BR 22	1	1	I&E 05	2	2
	LIC QUAL BR	1	1	MOORE, V.	1	1
	MPA 08	1	1	NRC PDR 02	1	1
	OELD 23	1	1	OR ASSESS BR 17	1	1
	PROC/IST REV BR	1	1	QA BR 10	1	1
	<u>REG FILE</u> 01	1	1	STANDRDS DEV 11	1	1
EXTERNAL:	ACRS 24	16	16	LPDR 03	1	1
	NSIC 04	1	1			

JUN 28 1980

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

June 20, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - BLOWN FUSES IN LOW VOLTAGE
SWITCHGEAR - NCR 994 - SECOND REVISED FINAL REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector Milton Hunt on April 25, 1979, in accordance with 10 CFR 50.55(e). This was followed by our interim reports dated May 25 and July 19, 1979, our final report dated September 5, 1979, our supplemental report dated October 15, 1979, and our revised final report on February 7, 1980. As a result of new information received subsequent to the last report as documented in NCR BLN EEB 8003 (nonreportable), an additional report is required. Enclosed is our second revised final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Bo 19
S/L

8 0062 50 227