



10 CFR 2.201
L-2011-083
MAR 8 2011

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555-0001

Re: Florida Power and Light Company
Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Reply to Notice of Violation: EA-10-241

Reference: NRC Letter to Florida Power and Light Company dated February 7, 2011

Florida Power and Light Company, the licensee for the Turkey Point Nuclear Plant, Units 3 and 4, hereby submits a Reply to the Notice of Violation contained in the above referenced correspondence. The Reply to the Notice of Violation is attached.

If there are any questions regarding this correspondence, please contact Mr. Robert Tomonto, Turkey Point Licensing Manager, at 305-246-7327.

Very truly yours,

Michael Kiley
Vice President
Turkey Point Nuclear Plant

Attachment: Reply to Notice of Violation: EA-10-241

cc: Regional Administrator, USNRC, Region II
Senior Resident Inspector, USNRC, Turkey Point

IED1
NRR

ATTACHMENT

Reply to Notice of Violation: EA-10-241

The NRC Letter to Florida Power and Light Company (FPL) dated February 7, 2011 identified a violation of NRC requirements. The violation and FPL's reply follow.

Violation

10 CFR 73.22(c)(2) states that while unattended, Safeguards Information (SGI) must be stored in a locked security storage container.

Contrary to the above, from November 9, 2009 through March 17, 2010, the licensee failed to store SGI in a locked security storage container while unattended. Specifically, an NRC force-on-force inspection report was stored in an unlocked desk drawer but within the protected area.

FPL Reply

FPL admits the violation.

Reasons for the Violation

The process for receipt of NRC SGI correspondence lacked sufficient rigor. The process allowed personnel that lack a high level of SGI awareness to receive documents containing SGI for the station.

Corrective Steps Taken to Avoid Further Violations and the Results Achieved

The FPL nuclear fleet Regulatory Correspondence procedure was revised to specify that only the site Security manager and Nuclear Fleet Security be included on the NRC's Service List Distribution for SGI.

A request to the NRC for SGI distribution to site Security Managers and Nuclear Fleet Security only was made by FPL letter L-2010-145 dated August 3, 2010.

FPL fleet procedure SY-AA-102-1000, Safeguards Information Program, was revised to require Security to review distribution lists in NRC correspondence containing SGI. The purpose of the review is to verify that SGI has not been forwarded to personnel other than Security. Additional guidance for receiving NRC SGI correspondence was also incorporated for all personnel.

A job familiarization guide was implemented for executive administrative assistants which includes familiarity with SGI control. This action was intended as a defense-in-depth measure to ensure that this population of employees knows how to treat SGI in the event of receipt.

There have been no further instances of loss of control of NRC-sent SGI at Turkey Point.

Date When Full Compliance Will Be Achieved

Full compliance was achieved on March 17, 2010 when the uncontrolled SGI was placed into the SGI control program.