

March 28, 2011



Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Sir / Madam:

Subject: VIRGIL C. SUMMER NUCLEAR STATION (VCSNS) UNIT 1
DOCKET NO. 50-395
OPERATING LICENSE NO. NPF-12
NOTICE OF TIMELINESS REGARDING SUBMITTAL OF SUPPLEMENTAL
LICENSE EVENT REPORT (LER 2010-002-01)

Reference: Thomas D. Gatlin, SCE&G, letter to Document Control Desk, License Event Report (LER 2010-002-00) Unanalyzed Condition Due to Wiring Discrepancy in the "B" Emergency Diesel Generator (EDG) Appendix R Isolation Circuitry dated June 28, 2010

South Carolina Electric & Gas Company (SCE&G) stated in License Event Report (LER) 2010-002-00:

The cause of this event is still under investigation. Upon completion of the root cause analysis, cause and corrective actions will be identified in a supplemental report. The supplemental report is projected to be submitted by November 30, 2010.

To date the investigation has not been completed. The supplemental report will be submitted by April 30, 2011. The timeliness issue associated with this supplemental report has been entered into the station's corrective action program (CR-11-01115).

If you have any questions, please contact Mr. Bruce L. Thompson at (803) 931-5042.

Very truly yours,

Thomas D. Gatlin

WCM/TDG/sr

c: K. B. Marsh
S. A. Byrne
J. B. Archie
N. S. Carns
J. H. Hamilton
R. J. White
W. M. Cherry
V. M. McCree

R. E. Martin
NRC Resident Inspector
K. M. Sutton
NSRC
RTS (CR-11-01115)
File (818.07)
PRSF (RC-11-0043)

IE22
NRR