

A 15

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE 29-00139-05G

Licensee: E.R. SQUIBB AND SONS INC
Site of operation: NEW BRUNSWICK, NJ

INFORMATION ON EXACT AMOUNTS OF MATL WAS NOT NEEDED TO EVALUATE

- 1. License is nonsuspect because it was superceded by another license

THIS LICENSE WAS ELIMINATED FROM CONSIDERATION
The reason for elimination was: SUPERCEDED BY NEW LICENSE

Reviewer's comments concerning license 29-00139-05G

THIS WAS A DISTRIBUTION LICENSE WITH NO POSSESSION AUTHORIZED WHICH WAS SUPERSEDED BY LICENSE NUMBER 29-00139-07G ACCORDING TO A NRC MEMO DATED 9/12/86.

EXPERT SYSTEM EVALUATION WAS BASED ON THE
INVENTORY RECORD IN JOB 1296, BOX 02

Docket 30-11757

Licensee: E.R. SQUIBB AND SONS INC
Address: NEW BRUNSWICK, NEW JERSEY

Zip: 08903

This license was listed as SUPERCEDED BY ANOTHER LICENSE

Contents of the new license field 29-00139-07G

State of operation: NJ

Site used: NEW BRUNSWICK, NJ

This license did not authorize possession of material

Disposition information present: NO DISPOSITION INFORMATION GIVEN

There is an NRC verification letter in this license file

Remarks: DISTRIBN. LIC. NRC MEMO STATING THAT LIC WAS SUPERSEDED BY -07G LIC
JOB NUMBER: 1296 BOX NUMBER: 02

Date of last evaluation/revision: 06/03/93

Reviewer: BWK

A/15