




# JAS. W. GLOVER, LTD.

GENERAL CONTRACTORS

License No. ABC-3



## FAX TRANSMITTAL

- Faxed from Safety Dept. (808) 218-7591
- Faxed from Honolulu (808) 591-8978
- Faxed from Lihue (808) 246-6209
- Faxed from Hilo (808) 961-9237
- Faxed from Kona (808) 326-6017
- Faxed from HNL Estimating (808) 591-9174

Date: 3/25/11

TO: US Nuclear Regulatory Commission

FROM: RICHARD S GIBBIN

Attention: Ms Michelle Simmons

FAX NO.: 817-860-8188

Number of pages including cover sheet: 7

SUBJECT: NRC LICENSE # 53-29391-01

Message: General location update to licensed gauges & current LEAK TEST data

[ ] PLEASE CALL ME AT: \_\_\_\_\_

If you do not receive all the pages, please call the sender as soon as possible. Thank you.


<b>Honolulu</b> P.O. Box 579 • Honolulu, HI 96809 tel (808) 591-8977 • fax (808) 591-8978	<b>Hilo</b> 890 Lailani St. • Hilo, HI 96720 tel (808) 935-0871 • fax (808) 961-9237	<b>Kona</b> P.O. Box 4116 • Kailua-Kona, HI 96745 tel (808) 329-4113 • fax (808) 326-6017	<b>Lihue</b> P.O. Box 1929 • Lihue, HI 96766 tel (808) 245-3609 • fax (808) 246-6209
---	--	---	--

An Equal Opportunity Employer

574812



**JAS. W. GLOVER, LTD.**  
GENERAL CONTRACTORS  
License No. ABC-3



March 25, 2011

Ms. Michelle Simmons  
United States Nuclear Regulatory Commission: **Via Facsimile #:817-860-8188**  
Region IV  
612 East Lamar Boulevard, Suite 400  
Arlington, TX 76011-4125

RE: License # **53-29391-01**  
Nuclear Density Gauge Location update; Current Leak Test data

Ms. Simmons;

Attached are our latest Leak Tests per gauge by serial number; all comply.

To update our file with the latest in-state locations of our Seaman Nuclear Gauge locations:

**Jas W. Glover, Ltd.**; 890 Leilani Street Hilo, HI 96720;  
No Change: (2) Seaman Gauges Ser #s: **21056; 21148** remain on-site;


**Jas W Glover, Ltd.**; 3-0301 Kaumualii Highway, Lihue, HI 96766;  
Seaman Gauge Ser # **21252** currently at Seaman Nuclear Corporation factory, Oak Creek, WI for maintenance & electrical component repair; will be returned to Honolulu for present time when completed;  
Seaman Gauge Ser # **21322** transferred to Lihue, HI from Puunene, HI location via Honolulu;

**Black Maui Rose, LLC**; Camp 10, Firebreak Rd Puunene, HI 96784;  
Seaman Gauge Ser # **21322** transferred to Jas. W. Glover, Ltd., Lihue HI location;  
Presently there is no gauge on-site;

**Black Plumeria, LLC**; 248 Sand Island Access Rd, Honolulu, HI 96819  
Seaman Gauge Ser #: **21188** remains on-site; anticipate Seaman Gauge Ser # **21252** to be stored at this location until needed as replacement for maintenance or construction resumes at its Black Maui Rose, LLC location;

All gauges have been rotated to Seaman Nuclear Corporation for yearly maintenance, update, repairs, during December 2010 through March 2011 time frame.

**PLEASE NOTE for your records: New cell phone for undersigned: (808) 756-3899**

Very truly yours,  
  
Richard S. Gribbin  
Statewide Mgr – QC/QA; RSO

Attachments (5)

**Honolulu**  
P.O. Box 579 • Honolulu, HI 96809  
tel (808) 591-8977 • fax (808) 591-8978

**Hilo**  
890 Leilani St. • Hilo, HI 96720  
tel (808) 935-0871 • fax (808) 961-9237

**Kona**  
P.O. Box 4116 • Kailua-Kona, HI 96745  
tel (808) 329-4113 • fax (808) 326-6017

**Lihue**  
P.O. Box 1929 • Lihue, HI 96766  
tel (808) 245-3609 • fax (808) 246-6209

Mar 25 11 10:13a

Richard S. Gribbin

8082179280

p. 1

## Seaman Nuclear Corporation

7315 South First Street Oak Creek, WI 53154 USA

Tel 414-762-5100 Fax 414-762-5106

### Leak Test Certificate

January 14, 2011

A leak test has been performed on meter, serial number **21056**, a model C-300 DT, 8", containing the radionuclide Ra 226.

Owned By: Jas. W. Glover Ltd.  
Attn: Rich Gribbin  
P.O. Box 579  
Honolulu, HI 96809

Date Sample Collected: 12/13/10  
Collected By: T. Lindemann  
Date Sample Analyzed: 1/5/11  
Analyzed By: T. Lindemann

Most regulatory agencies consider a source to be leaking if a leak test reveals the presence of more than 0.005 microcurie of removable contamination. Analysis was performed following this standard and no contamination was found.

Analysis is also capable of detecting 0.001 microcuries of radon-222, and 0.005 microcuries of any radium daughter which has a half-life longer than four days. Analysis was performed following this standard and no contamination was found.

Analysis authorized by Wisconsin license 079-1257-01.

Seaman Nuclear Corporation

**LEAK TEST DUE: 6/13/11**



Scott C. Seaman  
Radiation Safety Officer

## Seaman Nuclear Corporation

7315 South First Street Oak Creek, WI 53154 USA

Tel 414-762-5100 Fax 414-762-5106

### Leak Test Certificate

February 9, 2011

A leak test has been performed on meter, serial number **21148**, a model C-300 DT, 8", containing the radionuclide Ra 226.

Owned By: Jas. W. Glover Ltd.  
Attn: Rich Gribbin  
P.O. Box 579  
Honolulu, HI 96809

Date Sample Collected: 1/26/11  
Collected By: T. Lindemann  
Date Sample Analyzed: 2/3/11  
Analyzed By: T. Lindemann

Most regulatory agencies consider a source to be leaking if a leak test reveals the presence of more than 0.005 microcurie of removable contamination. Analysis was performed following this standard and no contamination was found.

Analysis is also capable of detecting 0.001 microcuries of radon-222, and 0.005 microcuries of any radium daughter which has a half-life longer than four days. Analysis was performed following this standard and no contamination was found.

Analysis authorized by Wisconsin license 079-1257-01.

Seaman Nuclear Corporation

**LEAK TEST DUE: 7/26/11**



Scott C. Seaman  
Radiation Safety Officer

# Seaman Nuclear Corporation

7315 South First Street Oak Creek, WI 53154 USA

Tel 414-762-5100 Fax 414-762-5106

## Leak Test Certificate

February 22, 2011

A leak test has been performed on meter, serial number **21188**, a model C-300, containing the radionuclide Ra 226.

Owned By: Jas. W. Glover Ltd.  
Attn: Rich Gribbin  
P.O. Box 579  
Honolulu, HI 96809

Date Sample Collected: 2/16/11  
Collected By: Rich Gribbin  
Date Sample Analyzed: 2/22/11  
Analyzed By: T. Lindemann

Most regulatory agencies consider a source to be leaking if a leak test reveals the presence of more than 0.005 microcurie of removable contamination.

Analysis found contamination of less than 0.005 microcurie.

Analysis authorized by Wisconsin license 079-1257-01.

Seaman Nuclear Corporation

**LEAK TEST DUE: 8/16/11**



Scott C. Seaman  
Radiation Safety Officer

S/N: 21188  
Leak Tested: 2/16/11  
Due: 8/16/11  
 Seaman Nuclear Corporation  
Oak Creek, WI (414) 762-5100

# Seaman Nuclear Corporation

7315 South First Street Oak Creek, WI 53154 USA

Tel 414-762-5100 Fax 414-762-5106

## Leak Test Certificate

March 4, 2011

A leak test has been performed on meter, serial number **21322**, a model C-300 DT, 8", containing the radionuclide Ra 226.

Owned By: Jas. W. Glover Ltd.  
Attn: Rich Gribbin  
P.O. Box 579  
Honolulu, HI 96809

Date Sample Collected: 2/21/11  
Collected By: T. Lindemann  
Date Sample Analyzed: 3/4/11  
Analyzed By: T. Lindemann

Most regulatory agencies consider a source to be leaking if a leak test reveals the presence of more than 0.005 microcurie of removable contamination. Analysis was performed following this standard and no contamination was found.

Analysis is also capable of detecting 0.001 microcuries of radon-222, and 0.005 microcuries of any radium daughter which has a half-life longer than four days. Analysis was performed following this standard and no contamination was found.

Analysis authorized by Wisconsin license 079-1257-01.

Seaman Nuclear Corporation

**LEAK TEST DUE: 8/21/11**



Scott C. Seaman  
Radiation Safety Officer

# Seaman Nuclear Corporation

7315 South First Street Oak Creek, WI 53154 USA

Tel 414-762-5100 Fax 414-762-5106

## Leak Test Certificate

March 9, 2011

A leak test has been performed on meter, serial number **21252**, a model C-300 DT, 8", containing the radionuclide Ra 226.

Owned By: Jas. W. Glover Ltd.  
Attn: Rich Gribbin  
P.O. Box 579  
Honolulu, HI 96809

Date Sample Collected: 2/25/11  
Collected By: Darin F.  
Date Sample Analyzed: 3/9/11  
Analyzed By: T. Lindemann

Most regulatory agencies consider a source to be leaking if a leak test reveals the presence of more than 0.005 microcurie of removable contamination.

Analysis found contamination of less than 0.005 microcurie.

Analysis authorized by Wisconsin license 079-1257-01.

Seaman Nuclear Corporation

**LEAK TEST DUE: 8/25/11**



Scott C. Seaman  
Radiation Safety Officer

APR - 5 2011

This is to acknowledge the receipt of your letter/application dated 5/25/11, and to inform you that the initial processing, which includes an administrative review, has been performed.

DATE \_\_\_\_\_


There were no administrative omissions. Your application will be assigned to a technical reviewer. Please note that the technical review may identify other omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card:

The action you requested is normally processed within 90 days.

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 574812.  
When calling to inquire about this action, please refer to this mail control number.  
You may call me at (817) 860-8103.

Sincerely,  
  
Licensing Assistant

BETWEEN:

Accounts Receivable/Payable  
and  
Regional Licensing Branches

[ FOR ARPB USE ]  
INFORMATION FROM LTS

Program Code: 03121  
Status Code: Pending Amendment  
Fee Category: 3P  
Exp. Date:  
Fee Comments:  
Decom Fin Assur Req: N

### License Fee Worksheet - License Fee Transmittal

#### A. REGION

##### 1. APPLICATION ATTACHED

Applicant/Licensee: JAS. W. GLOVER HOLDING CO, LTD AND  
Received Date: 03/25/2011  
Docket Number: 3038297  
Mail Control Number: 574812  
License Number: 53-29391-01  
Action Type: Amendment

##### 2. FEE ATTACHED

Amount: \_\_\_\_\_

Check No.: \_\_\_\_\_

##### 3. COMMENTS

Signed: Colleen Murahan

Date: 4-01-2011

#### B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered / / )

1. Fee Category and Amount: \_\_\_\_\_

##### 2. Correct Fee Paid. Application may be processed for:

Amendment: \_\_\_\_\_

Renewal: \_\_\_\_\_

License: \_\_\_\_\_

3. OTHER \_\_\_\_\_

Signed: \_\_\_\_\_

Date: \_\_\_\_\_