

REVIEW OF FILES AT THE ENTERGY WHITE PLAINS OFFICE

outside-of-scope

Document ID	Description
2005-017	Proposed Tech Spec Change - EPU - RAI Response
2005-028	Response to NRC-BL-2005-001 - MC&A
2005-085	Revised COLR report for Cycle 24
2005-094	Revision to Control Rod operability SCRAM time testing and Control Rod Accumulators RAI

Outside of Scope

CH

outside-of-scope

2005-102	COLR Report for Cycle 25	Outside of Scope
2005-101	TS PC 263-EPU-FW transient tstng	
2005-103	TS PC 263 – EPU – Steam Dryer inspection results	
2005-093	Notice of intent to submit LRA	
2005-095	License restriction due to change in med condition	
2005-084	EPU Supp 33	
2005-086	EPU Supp 34	
2005-040	RAI fir ILRT extension	

outside-of-scope

2005-033	Status of decommissioning funding
2005-032	Response to RAI - IRFM ST freq
2005-031	Sources and levels of insurance reqd by 10cfr50.54(w)
2005-030	EPU RAI Supp 25
2005-027	Supp to relief req RI-01
2005-023	SRO Lic exam results
2005-020	Response to NOV (pop in EPZ that cannot hear sirens and don't have TARs)
2005-011	Prop change to DW spray hdr and nozzle air tst freq supp
2005-010	Req to use diff ed of ASME code
2005-047	Rspns to SGI advisory

Outside of Scope

outside-of-scope

2005-055	2004 annual rad env report	Outside of Scope
2005-056	2004 annual rad eff report	
2005-064	LER 2004-003-01	
2005-069	RAI rsp for info for conducting SFP assessments	
2005-081	Supp Rspns to RAI for info for conducting SFP assessments	
2005-059	Revised RAI response re relief request Ri-01	
2005-087	LER 2005-001	
2005-104	LER 2005-002	
2005-105	Correction to TS pages	
2006-009	License renewal application	

outside of scope

		Outside of Scope
2006-023	COLR for Cycle 25	
2006-031	Commitment Rev 1 to steam dryer monitoring plan	
2006-039	Commitment Rev 2 to SDMP	

outside-of-scope

		Outside of Scope
2006-042	Commitment Rev 2 to SDMP	
2006-056	Report on SDMP results	
2006-060	SCRAM time testing RAI rpsns	
2006-063	LRA Amend 4	
2006-064	LRA Amend 5	
2006-068	Cycle 25 Startup test report	
2006-076	LRA Amend 8	

outside-of-scope

2006-083	LRA Amend 12
2006-090	LRA Amend 15
2006-091	LRA Amend 16
2006-095	LRA Amend 18
2006-096	LRA Amend 17
2006-097	LRA Amend 19
2006-098	LRA Amend 20
2006-099	LRA Amend 21
2006-100	LRA Amend 22
2006-066	Groundwater Protection

Outside of Scope

outside-of-scope

	Questionnaire	Outside of Scope
2006-038	Rspns to GL 06-02	
2006-036	UFSAR Rev 20	
2006-019	EPU- Dryer Flow induced vibration info	
2009-001	Cycle 26 50.59 report	
2009-003	Medical certificates & and prelim qual statements for lic cands	
2009-004	50.46(a)(3)(ii) Annual Report for 2008 (Changes in peak cladding temp)	
2009-008	Final 398 reports for lic cands	
2009-025	Operator re-application	
2009-033	Final 398 form submittal	

outside-of-scope

		Outside of Scope
2009-047	Licensed operator renewal	
2009-056	ISFSI annual eff report	
2009-066	50.55(a)(3)(i) ISI request	
2009-035	TS proposed change	
2009-037	2008 Rad eff release report	
2009-039	E Plan implementing proc chng	
2009-072	TS Bases pages	
ENOC-07-036	Response to Rqst for investigation (RI-2007-A-0054)	

outside-of-scope

ENOC-07-039	Response to Rqst for investigation (RI-2007-A-0123))	Outside of Scope
ENOC-09-042	Response to Rqst for investigation (RI-2009-A-0097)	
ENOC-08-031	Notice of trustee for decom funds	
ENOC-07-031	Response to Rqst for investigation (RI-2007-A-0054)	
ENOC-06-022	Response to Rqst for investigation (RI-2006-A-0133)	
ENOC-06-014	Response to Rqst for investigation (RI-2006-A-0051)	
ENOC-06-003	Response to Rqst for investigation (RI-2006-A-0178)	
ENOC-06-006	Response to Rqst for investigation (RI-2006-A-0034)	
CNRO-06-003	Supp to 30d rspns to NRC-BL-2005-002, EP and rspns actions for security-based events	
CR 2005-1318	Vermont Yankee Condition Report	

outside-of-scope

		Outside of Scope
CR 2005-1605	Vermont Yankee Condition Report	
CR 2005-1633	Vermont Yankee Condition Report	
CR 2005-2472	Vermont Yankee Condition Report	
CR 2005-3245	Vermont Yankee Condition Report	
CR 2006-3391	Vermont Yankee Condition Report	
CR 2006-3465	Vermont Yankee Condition Report	
CR 2006-3473	Vermont Yankee Condition Report	
CR 2007-0570	Vermont Yankee Condition Report	
CR 2007-2844	Vermont Yankee Condition Report	
CR 2007-4439	Vermont Yankee Condition Report	
CR 2007-4443	Vermont Yankee Condition Report	
CR 2007-4509	Vermont Yankee Condition Report	
CR 2008-0829	Vermont Yankee Condition Report	
CR 2008-1317	Vermont Yankee Condition Report	
CR 2008-2829	Vermont Yankee Condition Report	
CR 2008-3204	Vermont Yankee Condition Report	
CR 2008-5015	Vermont Yankee Condition Report	
CR 2008-5073	Vermont Yankee Condition Report	

outside-of-scope

		Outside of Scope
CR 2009-1416	Vermont Yankee Condition Report	
CR 2009-2530	Vermont Yankee Condition Report	
CR 2009-3420	Vermont Yankee Condition Report	
CR 2009-3516	Vermont Yankee Condition Report	
CR 2009-3918	Vermont Yankee Condition Report	
CR 2010-0204	Vermont Yankee Condition Report	
CR 2010-0632	Vermont Yankee Condition Report	
MLB Safety Culture Report – including transmittal letter from Janet Ecker, Sr. Counsel, to Charlene Fazon, Entergy, dated March 31, 2010		
2007-003	License Renewal Application Amendment 23	
2007-009	License Renewal Application Amendment 24	
2007-012	License Renewal Application Amendment 25	
2007-018	License Renewal Application Amendment 26	
2007-034	License Renewal Application Annual Update	
2007-047	License Renewal Application Amendment 27	
2007-054	License Renewal Application	

outside-of-scope

	Amendment 28	Outside of Scope
2007-058	License Renewal Application Amendment 29	
2007-061	VY Summary Reports for ISI and Repairs and Replacements	
2007-066	License Renewal Application Amendment 31	
2007-068	Confidential – Follow-up on operator FFD	
2007-069	VY Emergency Plan Implementing Procedures	
2007-070	VY Emergency Plan R 43	
2007-071	Resubmittal of Relief Request No. ISI-PT-01	
2007-076	License Renewal Application Amendment 32	
2007-079	VY Update of Aging Management Program Audit Q&A Database	
2007-082	License Renewal Application Amendment 33	
2008-001	Technical Specification Change #273	
2008-002	License Renewal Application Amendment 34	
2008-003	Emergency Plan Change	
2008-004	Emergency Plan Implementing Change	
2008-005	10 CFR 50.46 Annual Report for 2007	
2008-006	Licensed Operator Change in Medical Condition	
2008-007	Revision to TS section 3.3/4.3	
2008-008	License Renewal Application Amendment 35	
2008-009	VY Response to NRC Bulletin 2007-	

outside-of-scope

	01
2008-010	Report pursuant to 10 CFR 50.75
2008-011	Termination of Operator License
2008-012	License Renewal Application Amendment 36
2008-013	Deviation from BWRVIP-130
2008-014	FFD Performance Report for July 2007-December 2007
2008-015	Licensed Operator Change in Medical Condition
2008-016	License Renewal Final Safety Evaluation Report Comments
2008-017	Decommissioning Fund Status Report
2008-018	Physical Security, Safeguards Contingency and Training and Qualification Plan, Rev. 5
2008-019	Change of Emergency EALs
2008-020	VY three month response to Generic Letter 2008-01
2008-021	Application for SRO license
2008-022	RAI Response - Spent Fuel Management Plan
2008-023	2007 Annual Report of Individual Monitoring
2008-024	E-Plan Implementing Procedure Change
2008-025	Nuclear Onsite Property Damage Ins.
2008-026	Licensed Operator change in medical condition
2008-027	Update to VY Security Plan List of Changes
2008-028	Security Event Report

Outside of Scope

outside-of-scope

2008-029	2007 Radioactive Effluent Release Report
2008-030	2007 Annual Radiological Environmental Operating Report
2008-031	Revised TS bases change
2008-032	ISFSI – Registration of 1 st cask in use
2008-033	Re-submittal of Safeguards Information
2008-035	Change of Emergency Action Levels Basis to NEI 99-01 Rev. 5
2008-037	Commitment Change for Control Room HVAC Isolation Test Periodicity
2008-038	ISFSI Registration of 2 nd cask in use
2008-039	Operator License Renewals
2008-040	Request for Revision to Existing 10 CFR 50 Appendix R Exemption
2008-041	ISFSI Registration of 3 rd cask in use
2008-042	Termination of Operator License
2008-043	Commitment Change for Station Blackout Testing
2008-044	ISFSI Registration of 4 th cask in use
2008-045	LER 08-001-00 Crane Travel Stops
2008-046	Revision of Technical Specification Bases Pg 97
2008-047	PC 276 Response to Request for Add'l Information
2008-048	Bulletin 2007-01 RAIs

Outside of Scope

outside-of-scope

2008-049	Response to Regulatory Issue Summary 2008-16
2008-050	PC 273 Supp 1
2008-051	VY Registration of Spent Fuel Cask use
2008-052	MSIV Testing TS Change PC 278
2008-053	PC 279 Section 5.1 Tech Specs
2008-054	Licensed Operator change in <i>medical condition</i>
2008-055	PC277 Name Change
2008-056	E-Plan Rev 45
2008-057	E-Plan Implementation Change
2008-058	VY UFSAR Electronic Resubmittal
2008-059	PC280 Relocate RB Crane Tech Spec to TRM
2008-060	Delete words in 480V UPS Tech Spec Bases
2008-061	Licensed Operator change in <i>medical condition</i>
2008-062	PC 273 Supp 2
2008-063	Licensed Operator change in <i>medical condition</i>
2008-064	FFD Performance Report Jan 2008 - June 2008
2008-065	Control System Vulnerability RAI Response
2008-066	LA 232 corrected page 152
2008-067	Cancellation of Operator License
2008-068	Cancellation of Operator License
2008-069	TS PC 281 - Revision to Battery

Outside of Scope

outside-of-scope

	System	Outside of Scope
2008-070	PC 273 Supp 3 – Response to Additional RAI Related to Degraded Grid Protection	
2010-001	10 CFR 50.46 Annual Report for 2009	
2010-005	Licensed Operator Renewal	
2010-010	License Renewal – Buried Piping	