

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  
Berland Diagnostic Imaging Center of  
Creve Coeur  
774 North New Ballas Road  
Creve Coeur, MO 63141

2. NRC/REGIONAL OFFICE  
U.S. Nuclear Regulatory Commission  
Region III  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4351

REPORT NUMBER(S) 2011-001

3. DOCKET NUMBER(S)  
030-34988

4. LICENSEE NUMBER(S)  
24-32071-02

5. DATE(S) OF INSPECTION  
February 28-March 9, 2011

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied

\_\_\_\_\_ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura		3/10/2011
Branch Chief	Tamara E. Bloomer		3/10/2011

NRC FORM 591 M PART 3  
(06-2010)  
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

*Docket File Information*  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE Berland Diagnostic Imaging Center of Creve Coeur 774 North New Ballas Road Creve Coeur, MO 63141 REPORT NUMBER(S) 2011-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4351	
3. DOCKET NUMBER(S) 030-34988		4. LICENSE NUMBER(S) 24-32071-02	5. DATE(S) OF INSPECTION February 28-March 9, 2011
6. INSPECTION PROCEDURES 87130		7. INSPECTION FOCUS AREAS 03.01-03.08	
<b>SUPPLEMENTAL INSPECTION INFORMATION</b>			
1. PROGRAM 02201	2. PRIORITY 5	3. LICENSEE CONTACT Robert Seeling, M.D., RSO	4. TELEPHONE NUMBER 314-567-1656
<input checked="" type="checkbox"/> Main Office Inspection      Next Inspection Date: <u>March 2016</u> <input type="checkbox"/> Field Office Inspection <input type="checkbox"/> Temporary Job Site Inspection _____			

**PROGRAM SCOPE**

This licensee was an independent diagnostic clinic with authorization to use licensed material permitted by Sections 35.100, and 35.200. According to the licensee's records, the last patient study occurred in May 2008. The licensee possessed no RAM. All material was either held for DIS or transferred to an licensed waste broker for disposal. In summer 2010, the licensee inquired about terminating its NRC license. At the time of this inspection, the licensee filed a request to terminate its NRC license in November 2010. Although the original request was voided by MLB for insufficient information, the licensee submitted additional information to support its application.

This inspection consisted of interviews with select licensee personnel; a review of select records; a tour of the former nuclear medicine department; and independent measurements. The inspector advised the licensee to remove "CRAM" signage in the old imaging room. The inspection included in office review through March 9, 2011, to confirm that the licensee's termination request was reactivated and pending review by MLB.