



Dante C
Huntsman/DHUN/CC01/INEE
L/US

05/23/2005 09:51 AM

To Dante C Huntsman/DHUN/CC01/INEEL/US@INEL

cc

bcc

Subject Fw: Information request for NMED item 050121

----- Forwarded by Dante C Huntsman/DHUN/CC01/INEEL/US on 05/23/2005 09:51 AM -----



"Kevin Null" <KGN@nrc.gov>

05/23/2005 09:35 AM

To <NMED@inel.gov>

cc

Subject Re: Information request for NMED item 050121

Cause of the event: Misidentification of the base of the prostate due to the patient's size and weight.

Corrective actions: Procedures used to locate the prostate will include fluoroscopy, in addition to ultrasonic imaging.

>>> dante.huntsman@inl.gov 05/20/05 11:10AM >>>

We need additional information to complete the NMED record identified below. To promptly complete the NMED record, we request a reply at your earliest convenience, but no later than 60 days from the date of this request.

NMED Item No.: 050121
Licensee/Reporting Party: V.A., DEPARTMENT OF
License Number: 03-23853-01VA
Event Date: 2/24/2005

ADDITIONAL INFORMATION REQUESTED

What was the cause of the event (failed to verify treatment site, personnel error, etc.)?

What corrective action(s) were taken by the licensee to prevent a recurrence?

Thank you for your help,

Dante Huntsman
NMED Project
dhun@inel.gov