



Entergy Nuclear Northeast
Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, N.Y. 10511-0249
Tel (914) 734-6710

Robert Walpole
Licensing Manger

NL-11-051

April 11, 2011

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Technical Specification 5.6.8 – IP3 Steam Generator Tube Inspection Report -
Spring 2011 Refueling Outage
Indian Point Unit No. 3
Docket No. 50-286
License No. DPR-64

Dear Sir or Madam:

Technical Specification, 5.6.8, requires that a report be submitted to the NRC 180 days after the initial entry into Mode 4 following completion of a steam generator program inspection. This letter documents that Entergy Nuclear Operations, Inc. was not required to perform any inspection in the spring 2011 refueling outage, and therefore no formal report is required to be submitted in accordance with Technical Specification 5.6.8.

The next planned steam generator tube integrity inspection for Indian Point Unit 3 is scheduled for spring 2013, Refueling Outage 3R17. The previous inspection was performed during the spring 2007, Refueling Outage 3R14.

There are no new commitments contained in this letter. If you have any questions or require additional information, please contact me at 914-734-6710.

Sincerely,

A handwritten signature in black ink, appearing to read "RW", with a large, stylized flourish extending to the right.

RW/mb

cc: next page

A001
NRK

cc: Mr. William Dean, Regional Administrator, NRC Region 1
Mr. John Boska, Senior Project Manager, NRC NRR DORL
Mr. Peter Habighorst, Material Control and Accounting Branch, NRC
IPEC NRC Resident Inspector's Office
Mr. Francis J. Murray, President and CEO, NYSERDA
Mr. Paul Eddy, New York State Department of Public Service