

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

34 NOV 26

P 2: 30

November 20, 1984

U.S. Nuclear Regulatory Commission
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - SECOND SUPPLEMENTAL RESPONSE TO VIOLATION - 50-438/84-03-01, 50-439/84-03-01 - FAILURE TO FOLLOW PROCEDURES FOR CONCRETE EXPANSION ANCHOR BOLTS AND PIPE SUPPORT INSPECTIONS

TVA's initial response to R. C. Lewis' letter dated February 29, 1984, report numbers 50-438/84-03 and 50-439/84-03, concerning activities at the Bellefonte Nuclear Plant which appeared to have been in violation of NRC regulations was submitted on March 30, 1984. This was followed by our supplemental response submitted on August 3, 1984. Below is our second supplemental response.

As discussed with NRC-OIE Inspector Paul Fredrickson of October 30, 1984, the date of October 31, 1984 for completion of corrective actions indicated in our final report on this matter would not be met. Due to the length of Quality Control Procedure (QCP) 2.8, TVA had considered splitting this QCP into two separate procedures. Although this alternative is no longer being considered, the revision of QCP 2.8 has subsequently been delayed. The corrective action on this matter will be completed by January 11, 1985.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Domer

J. A. Domer
Nuclear Engineer

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8503010253 841120
PDR ADOCK 05000438
Q PDR

IF-01/10