



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532-4352

April 28, 2011

Ms. Julia Arthur
Testing Manager
ProMedica Northwest Ohio Cardiology Consultants, LLC
2940 North McCord Rd.
Toledo, OH 43615

SUBJECT: NRC ROUTINE INSPECTION REPORT NO. 150-00034/11-01(DNMS) –
PROMEDICA NORTHWEST OHIO CARDIOLOGY CONSULTANTS, LLC

Dear Ms. Arthur:

On April 15, 2011, a U.S. Nuclear Regulatory Commission (NRC) inspector conducted an inspection of your activities at a job site in Monroe, Michigan. The activities were authorized under Title 10 of the Code of Federal Regulations (10 CFR), Section 150.20, "Recognition of Agreement State Licenses."

This inspection did not identify any violations of NRC regulations; therefore, the NRC is issuing the enclosed NRC Form 591M for State of Ohio License No. 022200490001. You are not required to respond to this letter or the 591M.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

If you have any questions regarding this inspection, please feel free to contact me. You can reach me at 630-829-9627.

Sincerely,

A handwritten signature in cursive script that reads "Tamara E. Bloomer".

Tamara E. Bloomer, Chief
Materials Inspection Branch
Division of Nuclear Materials Safety

Docket No. 150-00034
Ohio License No. 02220490001

Enclosure: NRC Form 591M, Part 1

cc: State of Ohio

Ms. Julia Arthur
Testing Manager
ProMedica Northwest Ohio Cardiology Consultants, LLC
2940 North McCord Rd.
Toledo, OH 43615

SUBJECT: NRC ROUTINE INSPECTION REPORT NO. 150-00034/11-01(DNMS) –
PROMEDICA NORTHWEST OHIO CARDIOLOGY CONSULTANTS, LLC

Dear Ms. Arthur:

On April 15, 2011, a U.S. Nuclear Regulatory Commission (NRC) inspector conducted an inspection of your activities at a job site in Monroe, Michigan. The activities were authorized under Title 10 of the Code of Federal Regulations (10 CFR), Section 150.20, "Recognition of Agreement State Licenses."

This inspection did not identify any violations of NRC regulations; therefore, the NRC is issuing the enclosed NRC Form 591M for State of Ohio License No. 022200490001. You are not required to respond to this letter or the 591M.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

If you have any questions regarding this inspection, please feel free to contact me. You can reach me at 630-829-9627.

Sincerely,

/RA/

Tamara E. Bloomer, Chief
Materials Inspection Branch
Division of Nuclear Materials Safety

Docket No. 150-00034
Ohio License No. 02220490001

Enclosure: NRC Form 591M, Part 1

cc: State of Ohio

DISTRIBUTION:

Cynthia Pederson
Anne Boland
Patrick Louden

Steven Orth
Carole Ariano
Paul Pelke

Patricia Buckley
Tammy Tomczak
MIB Inspectors

DOCUMENT NAME: G:\DNMS\Work in progress\LTR -ProMed NW OH Cardio - Recy - CL.docx
 Publicly Available Non-Publicly Available Sensitive Non-Sensitive
To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

| | | | | |
|--------|-----------------|---------------|-----------|------|
| OFFICE | RIII DNMS | RIII DNMS | RIII DNMS | RIII |
| NAME | GMWarren:rj gmw | TEBloomer TEB | | |
| DATE | 04/27/2011 | 04/28/2011 | | |

OFFICIAL RECORD COPY

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| | |
|---|---|
| 1. LICENSEE/LOCATION INSPECTED: ProMedica Northwest Ohio Cardiology Consultants, LLC Toledo, Ohio Location: 219 W. Front Street, Monroe, Michigan REPORT NUMBER(S): 11-01 | 2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission, Region III 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532 |
|---|---|

| | | |
|--|---|--|
| 3. DOCKET NUMBER(S) 150-00034 (reciprocity) | 4. LICENSEE NUMBER(S) Ohio 02220490001 | 5. DATE(S) OF INSPECTION April 15, 2011 |
|--|---|--|

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied
 _____ Non-cited violation(s) were discussed involving the following requirement(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| Title | Printed Name | Signature | Date |
|---------------------------|--------------------|--|---------|
| LICENSEE'S REPRESENTATIVE | | | |
| NRC INSPECTOR | Geoffrey M. Warren |  | 4/28/11 |
| Branch Chief | Tamara E. Bloomer |  | 4/28/11 |

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| | |
|---|---|
| 1. LICENSEE ProMedica Northwest Ohio Cardiology Consultants, LLC Toledo, OH | 2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission, Region III 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532 |
|---|---|

REPORT NUMBER(S) 11-01

| | | |
|-----------------------------------|--|--|
| 3. DOCKET NUMBER(S) 150-00034 | 4. LICENSEE NUMBER(S) OH 02220490001 | 5. DATE(S) OF INSPECTION April 15, 2011 |
| 6. INSPECTION PROCEDURES 87130 | 7. INSPECTION FOCUS AREAS 03.01 – 03.07 | |

SUPPLEMENTAL INSPECTION INFORMATION

| | | | |
|---------------------|------------------|--|-------------------------------------|
| 1. PROGRAM 02220 | 2. PRIORITY 3 | 3. LICENSEE CONTACT Julia Arthur, Testing Manager | 4. TELEPHONE NUMBER 419-842-3006 |
|---------------------|------------------|--|-------------------------------------|

Main Office Inspection
 Field Office Inspection
 Temporary Job Site Inspection Dr. Abdul Kabir, 219 N. Front St, Monroe, MI

Next Inspection Date: TBD

PROGRAM SCOPE

The licensee provided mobile nuclear cardiology services in the Detroit area under reciprocity. At the job site in Monroe, Michigan, one technologist performed approximately 6 to 12 diagnostic cardiology procedures daily when on site, approximately twice monthly. A licensee nurse assisted on site but did not administer doses. Doses were received from a licensed nuclear pharmacy at the facility in Toledo, Ohio, assayed at that site, and transported to sites in Michigan. All waste was returned to the facility in Toledo for decay in storage.

Performance Observations

The inspector observed one diagnostic administration of licensed material, including dose verification and waste treatment. Licensee personnel demonstrated survey meter QC, transport of licensed material, and daily surveys and wipes. Interviews with licensee personnel indicated adequate knowledge of radiation safety concepts and procedures. The inspector performed independent and confirmatory radiation measurements which indicated results consistent with licensee survey records and postings.