

LEAK TEST CERTIFICATE

Wipe Date 4.15-2011

Instructions

- 1 Use wipe procedures as described in the device manual.
- 2 Enter all information under description.
- 3 Print or type return address in the space provided.
- 4 Wipe source (s) and put filter paper in the plastic bag.
- 5 Keep the middle copy and mail this form and bag to Humboldt.
- 6 Regulations require that sources with removable activity greater than 0.005 uCi be removed from service for repair and decontamination or disposal. Authorities must be notified.

DESCRIPTION OF DEVICE/SOURCE

Model 5001 Ser 284
 SOURCE 1 SOURCE 2
 Material CS 137 Am 241:Be
 Source Ser 70086F NJ00284
 RSO Name KENNETH EASTMAN
 Telephone (813) 925-1284

Do Not Write In This Space
For HSI Use Only

REMOVABLE ACTIVITY

Beta 0 uCi Alpha 0 uCi
 Humboldt Scientific
 By DOTU.
 Date 05/09/11

5200174
 Return
 Address
 Label
 Please
 Type or
 Print
 Clearly

- KIRK EASTMAN
 - 14660 CORKWOOD DRIVE
 - TAMPA, FL 33626
 -

HUMBOLDT SCIENTIFIC INC. 551D Pylon Drive, Raleigh, NC 27606, (919) 832-6509