

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

ENVIRONMENTAL

TO: J.G. Keppler

FROM: Wisconsin Public SVC. Corp.
Green, Bay, Wis.
E.W. James

DATE OF DOCUMENT

7-9-76

DATE RECEIVED

7-12-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1

DESCRIPTION Ltr. re our 7-2-76 ltr.
Ltr. trans the following.....

ENCLOSURE
Environmental Tech. Spec. Report # 76-3, on 6-30-76 concerning the turbine building sump that was not sampled and analyzed

(1 Signed Cy. Received)
(2 Pages)

DO NOT REMOVE
ACKNOWLEDGED

PLANT NAME: Kewaunee

SAFETY

FOR ACTION/INFORMATION

ENVIRO

SAB 7-16-76

ASSIGNED AD:		ASSIGNED AD:
BRANCH CHIEF:	Schwencer	BRANCH CHIEF:
PROJECT MANAGER:	Neighbors	PROJECT MANAGER:
LIC. ASST.:	Sheppard	LIC. ASST.:

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE	SYSTEMS SAFETY	PLANT SYSTEMS	SITE SAFETY &
<input checked="" type="checkbox"/> NRC PDR	HEINEMAN	TEDESCO	ENVIRO ANALYSIS
<input checked="" type="checkbox"/> I & E (2)	SCHROEDER	BENAROYA	<input checked="" type="checkbox"/> DENTON & MULLER
<input checked="" type="checkbox"/> OELD		LAINAS	
<input checked="" type="checkbox"/> GOSSICK & STAFF	ENGINEERING	IPPOLITO	ENVIRO TECH.
MIPC	MACCARRY	KIRKWOOD	ERNST
CASE	KNIGHT		<input checked="" type="checkbox"/> BALLARD
HANAUER	SINWEIL	OPERATING REACTORS	SPANGLER
HARLESS	PAWLICKI	STELLO	
			SITE TECH.
PROJECT MANAGEMENT	REACTOR SAFETY	OPERATING TECH.	GAMMILL
BOYD	ROSS	<input checked="" type="checkbox"/> EISENHUT	STEPP
P. COLLINS	NOVAK	SHAO	HULMAN
HOUSTON	ROSZTOCZY	BAER	
PETERSON	CHECK	BUTLER	SITE ANALYSIS
MELTZ		<input checked="" type="checkbox"/> GRIMES	<input checked="" type="checkbox"/> VOLLNER
<input checked="" type="checkbox"/> HELTEMES	AT & I		BUNCH
SKOVHOLT	SALTZMAN		<input checked="" type="checkbox"/> J. COLLINS
<input checked="" type="checkbox"/> Moore	RUTBERG		<input checked="" type="checkbox"/> KREGER

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> PDR: Kewaunee, Wis.	<input checked="" type="checkbox"/> NAT LAB: ANN (3)	BROOKHAVEN NAT LAB	CONTROL NUMBER 7147
<input checked="" type="checkbox"/> TIC:	REG. VIE	ULRIKSON (ORNL)	
<input checked="" type="checkbox"/> NSIC:	LA PDR		
<input checked="" type="checkbox"/> ASLB:	CONSULTANTS		
<input checked="" type="checkbox"/> ACRS 16 CYS HOLDING/SENT			

Regulatory

File Cy.

WISCONSIN PUBLIC SERVICE CORPORATION

Public Service



P.O. Box 1200, Green Bay, Wisconsin 54305

July 9, 1976

Mr. J. G. Keppler, Reg Dir
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



Dear Mr. Keppler:

Subject: Docket 50-305
Operating License DPR-43
Environmental Technical Specification
Report ETSR 76-3

In accordance with Environmental Technical Specifications 5.2a and 5.4c, the attached Environmental Report, ETSR 76-3, is being submitted.

We have received your letter dated July 2, 1976, which concurs with our opinion that the prompt reporting of environmental monitoring requirements is both a costly and a wasteful use of both WPS and NRC manpower. We would like to express our appreciation of your prompt reply and your interest in seeking improvement in this area of the Technical Specifications. We are taking immediate action to initiate a change to modify the reporting requirements for the Kewaunee Environmental Technical Specifications and presently anticipate submittal of the request for amendment by July 16, 1976.

Very truly yours,

E. W. James
Senior Vice President
Power Supply & Engineering

EWJ:sna
Enc.

- cc - Director, Office of Inspection & Enforcement
US NRC, Washington, D. C. 20555
- Director, Office of Management Information
and Program Control
US NRC, Washington, D. C. 20555
- Mr. Dwane Boyd, Resident Inspector
US NRC

714

ENVIRONMENTAL TECHNICAL SPECIFICATION REPORT
Number : ETSR 76-3

July 9, 1976

Kewaunee Nuclear Power Plant
Docket 50-305
Operating License DPR-43

Description of Event:

The turbine building sump was not sampled and analyzed for pH and suspended solids on 6/30/76. Environmental Technical Specifications requires daily sampling of the sump.

Cause of Event:

The person who normally performs this task was occupied with another task the entire shift and forgot to take the sample. A routine review of that day's log sheet detected the missed sample.

Environmental Implications:

There are no environmental implications. The specification requires a characterization of the sample from the turbine building sump. Characterization of previous and subsequent samples show little or no change in pH and suspended solids.

Corrective Measures:

The existing procedures and log sheets are sufficient to ensure daily sampling of the sump; and the person involved was informed of the consequences of the missed sample.