## WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

August 10, 1978

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305 Operating License DPR-43 IE Bulletin No. 78-10, Bergen-Paterson Hydraulic Shock Suppressor Accumulator Spring Coils

The referenced IE Bulletin concerns a problem experienced involving broken accumulator spring coils found in early model Bergen-Paterson hydraulic snubbers. The bulletin requests action by facilities that have Bergen-Paterson snubbers installed.

Bergen-Paterson hydraulic snubbers are not used at the Kewaunee Nuclear Power Plant. Therefore, IE Bulletin No. 78-10 does not apply to the Kewaunee Plant. No further action is planned regarding this bulletin.

Very truly yours,

E. W. James

Senior Vice Brestdent Power Supply & Engineering

 $\operatorname{snf}$ 

AUG 1 4 1978

cc - Dir, Office of Inspection & Enforcement US NRC, Washington, D. C. 20555