

February 4, 1977

TELEGRAM

50-305

Mr. D. Hunter
U.S. Nuclear Regulatory Commission
Directorate of Regulatory Operations - Region III
Glen Ellyn, Illinois 60137

SUBJECT: Docket 50-305
OPERATING LICENSE
REPORTABLE OCCURRENCE REPORT

In accordance with the requirements of Technical Specifications,
Paragraph 6.9.2.a.3 and 4.4.b.7, we submit the following:

Report Number: 50-305/77-2

Occurrence Date: February 3, 1977

Facility: Kewaunee Nuclear Power Plant
Kewaunee, Wisconsin 54216

Identification of Occurrence:

Containment Integrity as defined by 1.0.g.4 did not exist.

Condition Prior to Occurrence:

Cold Shutdown

Description of Occurrence:

While performing local leak rate surveillance test, containment
isolation valves RBV-1, RBV-2, RBV-3 and RBV-4 were found to
leak in excess of allowable limits.

CP Roma

rec'd 10:59 2/4/77
bk