MEMO ROUTE SLIP			See me about this.	For concurse.	For action.		
Form AEC-93 (Rev. May 14, 1947) AECM) AECM 0240	Note and return.	For signate	For information,		
TO (Nasio and uset) Initial		INITIALS	REMARKS				
RO Chief, FS&EB			Wisconsin Public Service Corporation				
RO:HQ (4)			Kewaunee	50-305			
Licensing (4)		DATE	L				
DR Central Files		1					
Region I							
TO (Name and unit)		INITIALS	REMARKS				
Region II							
Local PDR							
PDR		DATE'					
NSIC		Ì					
DTIE							
TO (Name and unit)		INITIALS REMARKS					
OGC, Beth, P-506A							
		DATE		•			
D. M. Hunnicutt		REMARKS Attached is a copy of licensee's adequate reply dated 4-18-74					
						to RO Bulletin 74-3.	
				\cdot			
PHONE NO.	6-4-74		· ·				

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO: 1971 O - 445-469

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

April 18, 1974

U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attention: Mr. James G. Keppler

Regional Director

Dear Sir:

Reference: Docket 50-305

Operating License DPR-43

Letter from Mr. J. G. Keppler to Mr. E. W. James dated April 2, 1974

The referenced letter transmitted Directorate of Regulatory Operations Bulletin No. 3 "Failure of Structural or Seismic Support Bolts on Class I Components" which requested specific information regarding our proposed schedule for inspection of a representative portion of the support members and structures, including bolting material for two Seismic Category I vessels and a date by which our detailed written programs and procedures will be available for RO inspection.

We intend to perform our selective examination of the materials during our first scheduled refueling. We will review our structures and bolting material and categorize the items that we believe should be examined. Upon completion of the review, we will commence preparation of the procedures which will identify the structures to be examined, inspection methods to be used and number of bolts per structure to be examined. We will have the procedures available for RO inspection within two months of the scheduled refueling.

Very truly yours,

E. W. James, Senior Vice President Power Generation & Engineering

EWJ:sna

cc - Dr. D. F. Knuth