


MEMO ROUTE SLIP		See me about this.	For concurrence.	For action.
Form AEC-93 (Rev. May 14, 1947) AECM 0240		Note and return.	For signature.	For information.
TO (Name and unit) RO Chief, FS&EB RO:HQ (4) Licensing (4) DR Central Files Region I	INITIALS	REMARKS Wisconsin Public Service Corporation Kewaunee 50-305		
	DATE			
TO (Name and unit) Region II PDR Local PDR NSIC DTIE	INITIALS	REMARKS		
	DATE			
TO (Name and unit) R. Renfrow, GC OGC, Beth, P-506A	INITIALS	REMARKS		
	DATE			
FROM (Name and unit) W. E. Vetter RO:III	REMARKS Attached is a copy of licensee's adequate reply dtd 8-22-73 to RO Bulletin 73-2.			
PHONE NO.	DATE 3-4-74			

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO : 1971 O - 445-469

LB

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

August 22, 1973

U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attention: Mr. Boyce H. Grier
Regional Director

Dear Sir:

Reference: Docket 50-305
Letter from Mr. B. H. Grier to Mr. E. W. James dated 7/27/73

The referenced letter transmitted Directorate of Regulatory Operations Bulletin No. 73-2, "Malfunction of Containment Purge Supply Valve Switches" which described a malfunction at another facility and a request for action to be taken by Wisconsin Public Service Corporation.

We have reviewed both Bulletin No. 73-2 and the design of our control circuits for the containment ventilation isolation system valves and have concluded that a failure of a single control switch cannot result in a simultaneous failure of the redundant supply or exhaust valves since the Kewaunee design utilizes separate and independent switches for valve operation. This is clearly shown on Figure 5.4-1 of the FSAR.

Very truly yours,

E. W. James, Senior Vice-President
Power Generation & Engineering

EWJ:sna

AUG 23 1973