

REPORT OF ABNORMAL OCCURRENCE AND/OR ACCIDENT

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 10108

FILE: INCIDENT REPORT FILE

FROM: Wisconsin Public Service Corporation Green Bay, Wis. 54305 E.W. James		DATE OF DOC 9-19-75	DATE REC'D 9-23-75	LTR XX	TWX	RPT	OTHER
TO: Mr. B.C. Rusche		ORIG 1 signed	CC	OTHER	SENT AEC PDR <u>XX</u>		SENT LOCAL PDR <u>XX</u>
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-305		

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Licensee Event Report No. A0-75-17 on 9-11-75 re both doors of the shield building air lock were open....

(1 cy encl rec'd)

PLANT NAME: Kewaunee Plant

ACKNOWLEDGED
Do Not Remove

FOR ACTION/INFORMATION DHL 9-26-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	✓ PURPLE (L) W/3 Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO ** STELLO ** HOUSTON ** NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON ** GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) ✓ S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	---	---	---	---

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Kewaunee, Wis.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST Sheppard 9-26-75		
** SEND ONLY TEN DAY REPORTS		

A0-4

[Handwritten signature]

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305


Regulatory Docket File

September 19, 1975

Mr. Benard Rusche, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Rusche:

Subject: Docket 50-305
Operating License DPR-43
Abnormal Occurrence Report AO 75-17



In accordance with the requirements of Technical Specifications,
paragraph 6.6.2, we submit the attached Licensee Event Report form for
Abnormal Occurrence AO 75-17.

Very truly yours,

E. W. James
Senior Vice President
Power Supply & Engineering

EWJ:sna
Attach.
cc - Mr. James G. Keppler, US NRC
Mr. Dwane Boyd, US NRC

80108

Keweenaw EVENT REPORT

Regulatory Docket File

CONTROL BLOCK:

--	--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	W	I	K	N	P	1
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	1
---	---

Category:

01	CON'T
----	-------

 Report Type:

L

 Report Source:

L

 Docket Number:

0	5	0	-	0	3	0	5
---	---	---	---	---	---	---	---

 Event Date:

0	9	1	1	7	5
---	---	---	---	---	---

 Report Date:

0	9	1	9	7	5
---	---	---	---	---	---

EVENT DESCRIPTION

02 During a scheduled maintenance outage with the reactor in the hot shutdown condition,
 03 the Shift Supervisor discovered on a plant tour that both doors of the Shield
 04 Building air lock were open in violation of the Keweenaw Plant Technical
 05 Specifications. This is event AO 75-17
 06

SYSTEM CODE:

Z	Z
---	---

 CAUSE CODE:

A

 COMPONENT CODE:

Z	Z	Z	Z	Z	Z
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

Z

 COMPONENT MANUFACTURER:

Z	9	9	9
---	---	---	---

 VIOLATION:

Y

CAUSE DESCRIPTION

06 This event was the result of personnel error. All personnel were instructed that
 09 one door in the shield building air lock must remain closed at all times unless the
 10 plant is in cold shutdown.

FACILITY STATUS:

D

 % POWER:

0	0	0
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

C

 DISCOVERY DESCRIPTION:

Shift Supervisor plant tour

 FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

13 NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

14 NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16 TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18

19

NAME: G. Kingston PHONE: 414/432-3311