

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 4582

FILE: INCIDENT REPORT FILE

FROM: Wisconsin Public Serv. Co. Green Bay, Wisc. E.W. James			DATE OF DOC 4-23-75	DATE REC'D 4-25-75	LTR xxxx	TWX	RPT	OTHER
TO: Edson Case			ORIG 1 Signed	CC	OTHER	SENT AEC PDR _____ SENT LOCAL PDR _____		
CLASS	UNCLASS xxxx	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-305		
DESCRIPTION: Ltr. trans the following..... DO NOT REMOVE ACKNOWLEDGE				ENCLOSURES: Abnorm. Occurr. # 75-7, on 4-16-75, concern- ing Failure of relay SIA-B2, Train B to latch in the energized position..... (1 cy. Encl. Rec'd)				
PLANT NAME: Kewaunee								

FOR ACTION/INFORMATION

VCR 4-28-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

REG FILE - NRC PDR - OGC, ROOM P-506A - GOSSICK/STAFF - CASE - GIAMBUSSO - BOYD - MOORE (L) - DEYOUNG (L) - SKOVHOLT (L) - GOLLER (L) (Ltr) - P. COLLINS - DENISE - REG OPR - FILE & REGION (2) - MIPC/PE (3) - STEELE	TECH REVIEW - SCHROEDER - MACCARY - KNIGHT - PAWLICKI - SHAO - **STELLO - **HOUSTON - **NOVAK - ROSS - IPPOLITO - TEDESCO - LONG - LAINAS - BENAROYA - VOLLMER	DENTON - **GRIMES - GAMMILL - KASTNER - BALLARD - SPANGLER ENVIRO - MULLER - DICKER - KNIGHTON - YOUNGBLOOD - REGAN - PROJECT LDR - HARLESS	LIC ASST - R. DIGGS (L) - H. GEARIN (L) - E. GOULBOURNE (L) - P. KREUTZER (E) - J. LEE (L) - M. MAIGRET (L) - S. REED (E) - M. SERVICE (L) - S. SHEPPARD (L) - M. SLATER (E) - H. SMITH (L) - S. TEETS (L) - G. WILLIAMS (E) - V. WILSON (L) - R. INGRAM (L)	A/T IND. - BRAITMAN - SALTZMAN - MELTZ PLANS - MCDONALD - CHAPMAN - DUBE (Ltr) - E. COUPE - PETERSON - HARTFIELD (2) - KLECKER - EISENHUT - WIGGINTON - F. WILLIAMS - HANAUER
---	--	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <i>Kewaunee Misc.</i>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS		

WISCONSIN PUBLIC SERVICE CORPORATION

Regulatory

File CYA

Public Service


P.O. Box 1200, Green Bay, Wisconsin 54305

April 23, 1975

Mr. Edson Case, Acting Director
Directorate of Licensing
Office of Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Case:

Subject: Docket 50-305
Operating License DPR-43
Abnormal Occurrence Report A0 75-7



In accordance with the requirements of the Kewaunee Technical Specifications, paragraph 6.6.2, we submit the attached Licensee Event Report form.

Yours very truly,

E. W. James, Senior Vice-President
Power Generation & Engineering

EWJ/ml
Attach.
cc: Mr. James G. Keppler
Mr. Dwane Boyd

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 W I K N P 1	LICENSE NUMBER 00-00000-00	LICENSE TYPE 41111	EVENT TYPE 01
CATEGORY 01 CONT	REPORT TYPE P O	REPORT SOURCE L L	DOCKET NUMBER 050-0305
EVENT DATE 041675		REPORT DATE 042375	

EVENT DESCRIPTION

02
During monthly surveillance test SP-155, step 5.11.2, relay SIA-B2, Train B did

03
not latch in the energized position. If an actual actuation signal had occurred,

04
the relay would have remained energized as long as the signal existed. Train A

05
was not affected and functioned properly. The mechanical latch was adjusted and

06
tested satisfactory.

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
S D	E	R E L A Y X	N	W 1 2 0	N

CAUSE DESCRIPTION

08
The mechanical latch did not function properly and when the test button was

09
released, the relay returned to the de-energized position.

10

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
E	099	NA	6	NA

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
Z	Z	NA	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	Z	NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION
000	NA

OFFSITE CONSEQUENCES

15
No danger to public health and safety

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
Z	NA

PUBLICITY

17
NA

ADDITIONAL FACTORS

18

19

NAME: M. E. Stern

PHONE: 414/432-3311