

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 1386

FILE: INCIDENT REPORT

FROM: Wisconsin Public Service Corp. Kewaunee, Wisconsin C.R. Luoma			DATE OF DOC 1-25-75	DATE REC'D 2-6-75	LTR XXXX	TWX	RPT	OTHER
TO: Mr. Duane Boyd			ORIG no	CC 1	OTHER	SENT AEC PDR <u>XXXX</u> SENT LOCAL PDR <u>XXXX</u>		
CLASS	UNCLASS XXXXXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-305		

DESCRIPTION:

Ltr reporting abnormal occurrence #75-4 on 1-24-75 concerning failure of 1A auxiliary feedwater pump to start

ENCLOSURES:

ACKNOWLEDGED

DON'T REMOVE

PLANT NAME:

Kewaunee

FOR ACTION/INFORMATION

2-7-75 JGB

BUTLER (S)	SCHWENCER (S)	ZIEMANN (S)	REGAN (E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK (S)	STOLZ (S)	DICKER (E)	LEAR (S)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
PARR (S)	VASSALLO (S)	KNIGHTON (E)	SPEIS (S)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL (S)	PURPLE (S)	YOUNGBLOOD (E)	
W/ Copies	W/4 Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC. ASST.</u>	<u>A/T IND</u>
✓ AEC PDR	✓ SCHROEDER	GRIMES	DIGGS (S)	BRAITMAN
✓ OGC, ROOM P-506-A	✓ MACCARRY	GAMMILL	GEARIN (S)	SALTZMAN
✓ MUNTZING/STAFF	✓ KNIGHT	✓ KASTNER	GOULBOURNE (S)	B. HURT
✓ CASE	✓ PAWLICKI	BALLARD	KREUTZER (E)	
GIAMBUSO	✓ SHAO	SPANGLER	LEE (S)	<u>PLANS</u>
BOYD	✓ STELLO		MAIGRET (S)	MCDONALD
MOORE (S) (BWR)	✓ HOUSTON	<u>ENVIRO</u>	REED (E)	CHAPMAN
DEYOUNG (S) (PWR)	✓ NOVAK	MULLER	SERVICE (S)	DUBE w/input
SKOVHOLT (S)	✓ ROSS	DICKER	✓ SHEPPARD (S)	E. COUPE
GOLLER (S)	✓ PIPPOLITO	KNIGHTON	SLATER (E)	✓ R. Hartfield (2)
P. COLLINS	✓ TEDESCO	YOUNGBLOOD	SMITH (S)	✓ KLECKER
DENISE	✓ LONG	REGAN	TEETS (S)	✓ F. WILLIAMS
<u>REG OPR</u>	✓ LAINAS	PROJECT LDR	WILLIAMS (E)	
✓ FILE & REGION	✓ BENAROYA		WILSON (S)	
✓ T.R. WILSON	✓ STEELE	<u>HARLESS</u>	INGRAM (S)	
	✓ VOLIMER			

EXTERNAL DISTRIBUTION

1-LOCAL PDR Kewaunee, Wisconsin	(1) (2) (10) - NATIONAL LABS	1-PDR SAN/LA/NY (4)
1-TIC (ABERNATHY)	1-W. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSON, ORNL
1-ASLB	NEWMARK/BLUME/AGBABIAN	1-AGMED (RUTH GUSSMAN)
1-NEWTON ANDERSON		RM B-127 G.T.
5-ACRS SENT TO LIC. ASST.		1-J. RUNKLES, RM E-201
		G.T.

SHEPPARD

TELEGRAM

Regulatory

January 25, 1975
File Cy.

Mr. Duane Boyd
Resident Inspector - U.S. Atomic Energy Commission
Directorate of Regulatory Operations - Region III
Two Rivers Municipal Hospital
Two Rivers, Wisconsin

SUBJECT: Docket 50-305
OPERATING LICENSE: DPR-43
ABNORMAL OCCURRENCE REPORT

In accordance with the requirements of Technical Specifications, Paragraph 6.6.2.a and 1.0a.1 (d), we submit the following:

Report Number: 50-305/75-4

Occurrence Date: January 24, 1975

Facility: Kewaunee Nuclear Power Plant
Kewaunee Wisconsin

Identification of Occurrence:

Failure of 1A Auxiliary Feedwater Pump to start

Condition Prior to Occurrence:

Reactor Critical - 73% Power
NORMAL Operating Temperature - 556° F Tavg
NORMAL Operating Pressure - 2235 psig

Description of Occurrence:

There was a failure of a power supply in the SCOTS system on the turbine. Failure of the power supply generated an overspeed trip signal which tripped the turbine and in turn the reactor. A Lo-Lo Steam Generator level was initiated and 1B and 1C Auxiliary Feed Water Pumps started and remained in operation. 1A Auxiliary Feed Water Pump did not start and upon investigation of breaker a contact on a switch was not closed. The breaker being used was the spare breaker while the breaker normally assigned to 1A Auxiliary Feed Water Pump was being checked. The spare breaker had been checked for operability.

C. R. Luoma