

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

CCESSION NBR: 7909110547 DOC. DATE: 79/09/07 NOTARIZED: NO DOCKET #
 FACIL: 50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Servic 05000305
 AUTH. NAME AUTHOR AFFILIATION
 RUITER, G. H. Wisconsin Public Service Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 79-022/03L-0 on 790808: during power assumption phase of
 plant startup, shift instrument channel checks not recorded
 Caused by operator negligence. Operators instructed on
 importance of fulfilling surveillance procedures.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Incident Reports

NOTES: I & E - 3 CYS ALL MATL. LAWRENCE (OELD) - 1 CY ALL MATL.

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
TION:	05 BC <u>ORB #1</u>	4 4		
TERNAL:	<u>01 REG FILE</u>	1 1	02 NRC PDR	1 1
	09 I&E	2 2	11 MPA	3 3
	14 TA/EDO	1 1	15 NOVAK/KNIEL	1 1
	16 EEB	1 1	17 AD FOR ENGR	1 1
	18 PLANT SYS BR	1 1	19 I&C SYS BR	1 1
	20 AD PLANT SYS	1 1	22 REAC SAFT BR	1 1
	23 ENGR BR	1 1	24 KREGER	1 1
	25 PWR SYS BR	1 1	26 AD/SITE ANAL	1 1
	27 OPERA LIC BR	1 1	28 ACIDENT ANALYS	1 1
	29 AUX SYS BR	1 1	E JORDAN/IE	1 1
	HANAUER, S.	1 1	STS GROUP LEADR	1 1
	TMI-H STREET	1 1		
TERNAL:	03 LPDR	1 1	04 NSIC	1 1
	29 ACRS	16 16		

SEP 13 1979

OTAL NUMBER OF COPIES REQUIRED: LTTR 52 ENCL 52

AO 4
 60

①

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

77

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

14

7 87 8/ 87 87 8

•

PHONE: (414) 433-1329

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	W	I	K	N	P	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5	
7	8	9	LICENSEE CODE				14	15	LICENSE NUMBER				25	26	LICENSE TYPE				30	57	CAT	58					59

0	1	L	6	0	5	0	0	0	3	0	5	7	0	8	0	8	7	9	8	0	9	0	7	7	9	9
7	8	REPORT SOURCE		60	61	DOCKET NUMBER				68	69	EVENT DATE				74	75	REPORT DATE				80				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the power assumption phase of plant startup, SP125 data, Shift Instrument

03 Channel Checks, was not recorded as required by TS 4.1.a during one shift. SP125

04 data taken before and after this event indicate normal instrument channel operations,

05 therefore, this event had no safety significance. No effect on plant operation or

06 public safety. SP 125 is performed each shift while operating to assure acceptable

07 operability of each instrument channel by comparison of the channel with other inde-

08 pendent instrument channels measuring the same variable.

0	9	I	E	11	A	12	A	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16			
7	8	SYSTEM CODE		9	10	CAUSE CODE		11	CAUSE SUBCODE		12	COMPONENT CODE				18	COMP. SUBCODE		19	VALVE SUBCODE		20

17	7	9	21	22	0	2	2	24	26	0	3	28	29	L	30	0	32					
7	8	LER/RO REPORT NUMBER		21	22	EVENT YEAR		23	SEQUENTIAL REPORT NO.		24	26	OCCURRENCE CODE		28	29	REPORT TYPE		30	REVISION NO.		32

X	18	H	19	Z	20	Z	21	0	0	0	0	22	N	23	N	24	Z	25	Z	9	9	9	26
33	34	ACTION TAKEN		35	EFFECT ON PLANT		36	SHUTDOWN METHOD		37	40	HOURS		41	ATTACHMENT SUBMITTED		42	PRIME COMP. SUPPLIER		43	COMPONENT MANUFACTURER		47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Because of involvement in plant startup activities the operators overlooked the

11 requirement to perform SP 125. As much data as possible was obtained from computer

12 logs. The involved operators were instructed on the importance of assuring that all

13 SP requirements are satisfied. During routine shift turnover, the operators review

14 plant indications and informally verify that indications agree with plant status.

1	5	C	28	0	9	0	29	Power Assumption	30	A	31	Operator observation	32			
7	8	FACILITY STATUS		9	% POWER		10	OTHER STATUS		30	METHOD OF DISCOVERY		45	DISCOVERY DESCRIPTION		80

1	6	Z	33	Z	34	NA	35	NA	36				
7	8	ACTIVITY RELEASED		9	CONTENT OF RELEASE		10	AMOUNT OF ACTIVITY		35	LOCATION OF RELEASE		36

1	7	0	0	0	37	Z	38	NA	39	
7	8	PERSONNEL EXPOSURES		9	NUMBER		10	DESCRIPTION		39

1	8	0	0	0	40	NA	41			
7	8	PERSONNEL INJURIES		9	NUMBER		10	DESCRIPTION		41

1	9	Z	42	NA	43					
7	8	LOSS OF OR DAMAGE TO FACILITY		9	TYPE		10	DESCRIPTION		43

2	0	N	44	NA	45		
7	8	PUBLICITY ISSUED		9	DESCRIPTION		45

NAME OF PREPARER G. H. RuiterPHONE: (414) 433-1329