



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
612 EAST LAMAR BLVD, SUITE 400
ARLINGTON, TEXAS 76011-4125

June 23, 2011

MEMORANDUM TO: Duane White, Health Physicist (MS-8F5)
Radioactive Materials Safety Branch
Division of Materials Safety & State Agreements

FROM: Vivian Campbell, Chief */RA/*
Nuclear Materials Safety Branch A
Division of Nuclear Materials Safety

SUBJECT: MATERIALS LICENSEE EVENT REPORT SUMMARY

Enclosed is the subject report for June, 2011. This enclosure documents the licensee event reports that were closed the preceding month(s), and lists ADAMS ML numbers for documents associated with these events, detailing Region IV's response to these events.

Enclosure:

June, 2011 RIV DNMS Licensee
Event Reports Summary Table

cc via email w/Enclosure 1:

- E. Collins
- A. Howell
- R. Caniano
- C. Cain
- V. Campbell
- J. Whitten
- D. Spitzberg
- J. Thompson
- D. Huntsman [Dante.Huntsman@inl.gov]
- LER File

S:\DNMS\INMIB\LERs\2011\5&6-2011.doc

ADAMS	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> SUNSI Review Complete	Reviewer Initials: JLT
	<input checked="" type="checkbox"/> Publicly Available		<input checked="" type="checkbox"/> Non-sensitive	
	<input type="checkbox"/> Non-publicly Available		<input type="checkbox"/> Sensitive	
KEYWORD: SUNSI Review Complete				
RIV:DNMS/NMSB-A		C:NMSB-A		
JLThompson		VHCampbell		
/RA/		/RA/		
06/16/2011		06/20/2011		

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - JUNE 2011

ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status
46450	12/2/2010	12/2/2010	Acuren	42-32443-01	10 CFR 30.50	Sealed source of Ir-192 failed to retract in Prudhoe Bay, Alaska during industrial radiography	Razo	Open
46466	12/2/2010	12/2/2010	Rio Tinto, Pacific Steel & Recycling	9999-0001 General License	10 CFR 20.2201	Discovery of a fixed nuclear gauge containing licensed material in a scrap yard	Razo	Open
ML111510906	5/25/2011	5/26/2011	National Oceanic & Atmospheric Admin.	46-23463-01	License Condition	Leaking foil source of Nickel-63 in an ECD within gas chromatograph	Hanson	Open
46757 ML111510866	4/15/2011	4/15/2011	TEAM Industrial Services, Inc.	42-32219-01	10 CFR 20.2201	Lost radiography camera during shipment containing 15 curies of Iridium-192	Poston	Open
ML111290769	3/30/2011	4/20/2011	Baker Hughes	17-27437-01	10 CFR 39.77	Well logging source abandonment involving 5 curie americium and 2.5 curie cesium sources	Thompson	Closed
ML111510933	4/29/2011	5/20/2011	Halliburton	42-01068-07	10 CFR 39.77	Well logging source abandonment involving a 2- curie cesium source	Thompson	Closed