

From: Gibson, Lauren
Sent: Wednesday, June 29, 2011 1:55 PM
To: Carl.Stephenson@aps.com
Cc: Russell.Stroud@aps.com
Subject: Questions concerning the Steam Generator Tube Inspection Report for Unit 3 RFO 15

Carl,

The NRC staff has a few questions from their review of the Steam Generator Tube Inspection Report for Unit 3 RFO 15, which was submitted on May 5, 2011. Please provide the answers to the questions below via e-mail no later than July 29, 2011.

1. Please confirm that no other secondary side inspections other than FOSAR and the inspection of the patch plate were performed during RFO 15
2. Please provide the cumulative effective full power years on the steam generators at the time of the RFO 14 and RFO 15 outages.

Please contact me if you would like to have a clarification call.

Thank you,
Lauren Gibson

Lauren K. Gibson
Project Manager, Palo Verde Nuclear Generating Station
Division of Operating Reactor Licensing
U.S. Nuclear Regulatory Commission
(301) 415-1056