

Entergy Nuclear Northeast Indian Point Energy Center 450 Broadway, GSB P.O. Box 249 Buchanan, N.Y. 10511-0249 Tel (914) 734-6710

Robert Walpole Licensing Manger

NL-11-050

June 20 2011

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

SUBJECT:

2011 Summary Reports for In-Service Inspection and

Repairs or Replacements at Indian Point Unit No.3

Indian Point Unit No. 3 Docket No. 50-286 License No. DPR-64

## Dear Sir or Madam:

In accordance with ASME Section XI, Code Case N-532-4, "Repair/Replacement Activity Documentation Requirements and In-service Summary Report Preparation and Submission" Indian Point Nuclear Generating Unit No.3 (IP3) hereby submits 2011 Form OAR-1, Owners Activity Report for Inservice Inspections. This report describes relevant conditions that required evaluation and repairs and replacements performed during the period April 2009 through April 2011.

There are no new commitments contained in this letter. If you have any questions or require additional information, please contact me at 914-734-6710.

Sincerely,

RW/mb

cc: next page

A047 MRR Enclosure: 1. 2011 Summary Reports for In-Service Inspection and

Repairs or Replacements at Indian Point Unit No.3

cc: Mr. William Dean, Regional Administrator, NRC Region 1

Mr. John Boska, Senior Project Manager, NRC NRR DORL

IPEC NRC Resident Inspector's Office

Mr. Francis J. Murray, President and CEO, NYSERDA

Mr. Paul Eddy, New York State Department of Public Service

## **ENCLOSURE 1 TO NL-11-050**

## 2011 Summary Reports for In-Service Inspection and Repairs or Replacements at Indian Point Unit No.3

ENTERGY NUCLEAR OPERATIONS, INC. INDIAN POINT UNIT 3 NUCLEAR POWER PLANT DOCKET No. 50-286

## FORM OAR-1 OWNERS ACTIVITY REPORT

Report Number: NL-11-050						
Plant Indian Point Energy Center, Buchanan, New York 10511-0249						
Unit No. 3 Commercial service date 08/30/1976 Refueling outage no. 3R16 (if applicable)						
Current inspection interval  (1st, 2nd, 3rd, 4th, Other)						
Current inspection period 1st (1st, 2nd, 3rd)						
Edition and Addenda of Section XI applicable to the inspection plans 2001 Edition, 2003 Addenda						
Date and revision of inspection plans: July 21, 2010 / ISI Program Plan, Rev. 1 No. SEP-ISI-IP3-001						
Edition and Addenda of Section XI applicable to repair/replacement activities, if different than the inspection plans _2001 Edition, 2003 Addenda						
Code Cases used: N-532-4, N-722, N-729-1 (if applicable)						
I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of3R16 conform to the requirements of Section XI.  (refueling outage number)  Signed Date						
CERTIFICATE OF INSERVICE INSPECTION						
I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province ofNew York and employed byHSB-CT ofHartford, Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.  By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or loss of any kind arising from or connected with this inspection.  CommissionsWS_10011_T, W_145_3084_ Inspector's Signature						
Date						

		TABLE				
ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE						
Examination Catagory and Item Number	Item Descrition	Evaluation Description				
N/A		None. During Indian Point Unit 3 outage, 3R16, there were no items with flaws or relevant conditions that required evaluation for continued service.				

5/23/2011 OAR-1

		TABLE 2					
ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE							
Code Class	Item Cescription	Description of Work	Date Completed	Repair/Replacement Plan Number			
N/A	N/A	None. There were no repair or reparements activities during the last reporting period that were required for continued service.					