PRIORITY 1 (ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9510180019 DOC.DATE: 95/09/30 NOTARIZED: NO DOCKET # FACIL: 50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Service AUTH.NAME AUTHOR AFFILIATION
ANDERSON, M.L. Wisconsin Public Service Corp.
MARCHI, M.L. Wisconsin Public Service Corp.
RECIP.NAME RECIPIENT AFFILIATION

R

I

0

R

I

T

Y

D

0

C

U

M

Ε

N

T

SUBJECT: Monthly operating rept for Sept 1995 for Kewaunee Nuclear Power Plant.W/951010 ltr.

DISTRIBUTION CODE: IE24D COPIES RECEIVED:LTR _ ENCL _ SIZE:_____
TITLE: Monthly Operating Report (per Tech Specs)

NOTES:

	RECIPIENT ID CODE/NAME PD3-3 PD	COPII LTTR 1	ES ENCL 1	RECIPIENT ID CODE/NAME LAUFER,R	COPI LTTR 1	
INTERNAL:	ACRS FILE CENTER 01 NRR/DRPM/PECB	10 1 1	10 1 1	AEOD/SPD/RRAB NRR/DISP/PIPB RGN3	1 1 1	1 1 1
EXTERNAL:	LITCO BRYCE,J H NRC PDR	1	1	NOAC	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 20

WPSC (414) 433-1598 TELECOPIER (414) 433-5544



600 North Adams ● P.O. Box 19002 ● Green 8ay, WI 54307-9002

October 10, 1995

10 CFR 50.36

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Ladies/Gentlemen:

Docket 50-305
Operating License DPR-43
Kewaunee Nuclear Power Plant
Monthly Operating Report

The narrative "Summary of Operating Experience" and completed forms covering plant and component availability for the Kewaunee Nuclear Power Plant for September 1995 are enclosed in accordance with Technical Specification 6.9.a.3.

Sincerely,

M. L. Marchi

Intracks

Manager-Nuclear Business Group

jmf

Enc.

cc - US NRC - Region 111 NRC Senior Resident Inspector INPO Records Center

170133

9510180019 950930 PDR ADDCK 05000305 R Test.

KEWAUNEE NUCLEAR POWER PLANT - DOCKET 50-305 SUMMARY OF OPERATING EXPERIENCE

September, 1995

A reactor trip occurred on 09-05-95 at 0838. The cause of the trip is suspected to have been a misaligned contact on a trip relay which completed the two out of four trip logic when the Presaurizer Low Pressure trip relay was tripped in as part of the SP test sequence. This is a suspected condition since inspections, testing, and computer and SER printout reviews did not confirm that a trip signal was initiated. The unit returned to full power on 09-06-95 at 1605 (96.1%, 527 MWEG) and has continued to operate at full power through the remainder of the reporting period.

The Instrument and Control group's activities for the month of September included the following:

- Supported the return of the plant to operation following the plant trip by the recalibration of Nuclear Instrument Channel N-36 rod stop and level trip setpoints
- Replacement of EQ coil on Main Feedwater valve 1B

When the plant was returned to operation, routine activities included:

- Replacement at power of three Pressurizer pressure low pressure trip relays in the train B Reactor Protection System using procedures from I & C Engineering
- Recalibration of A train hydro-pack pressure control switch
- Repair/recalibration of two Foxboro H line control boxes

Maintenance Work Request Summary for September

For both the Mechanical and Electrical areas routine repairs and Preventative Maintenance procedures were performed in the month of September. No significant failures or repairs were identified.

AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO- 50-305
UNIT- KEWAUNEE
COMPLETED BY- M. L. ANDERSON
TELEPHONE- 414-388-2560 X2453

REPORT MONTH SEPTEMBER, 1995

DAY	AVERAGE DAILY POWER LEVEL (MWE-NET)
123456789012345678901234567890	498 503 507 177 3022 598 498 4988 4903 5007 5007 5007 5007

DOCKET NO: UNIT NAME:

50-305 Kewaunee

DATE: COMP BY: October 6, 1995

TELEPHONE:

Mary L. Anderson 414-388-2560 x2453

UNIT SHUTDOWNS AND POWER REDUCTIONS REPORT MONTH - SEPTEMBER

NO.	DATE	TYPE	DURATION	REASON	METHOD	LER NO.	SYS	COMPONENT	COMMENTS
7	09-05-95	F	18.25	A should find the	3	95-006	IA	RELAYX	A Rx trip occurred 09-08-95 at 0836. The cause of the trip is suspected to have been a misaligned contact on a trip relay which completed the two out of four trip logic when the Pressurizer Low Pressure trip relay was tripped in as part of the SP test sequence.

TYPE

REASON

F: FORCED

S: SCHEDULED

A-Equipment Failure (explain) **B-Maintenance or Test**

C-Refueling

D-Regulatory Restriction

E-Operator Training & License Examination

F-Administrative

G-Operational Error (explain)

H-Other (explain)

METHOD

1-Manuai

2-Manuai Scram 3-Automatic Scram

4-Continuations 5-Load Reductions

9-Other

SYSTEM & COMPONENT CODES

From NUREG-0161

OPERATING DATA REPORT

OPERATING STATUS

DOCKET NO- 50-305 COMPLETED BY- M. L. ANDERSON TELEPHONE- 414-388-2560 X2453

2 REPORTING PERIOD SEPTEMBER, 1995

\$ NOTES

\$ N

8 IF CHANGES OCCUR IN CAPACITY RATINGS (ITEMS NUMBER 3 THROUGH 7) SINCE LAST REPORT, GIVE REASONS NONE

9 POWER LEVEL TO WHICH RESTRICTED, IF ANY (NET MWE) NONE

10 REASONS FOR RESTRICTIONS, IF ANY

		THIS MONTH	YR-TO-DATE	CUMULATIVE
11 HOUF	S IN REPORTING PERIOD	720	6551	186649
12 NUME	BER OF HOURS REACTOR WAS CRITICAL	703.3	5481.5	160256.5
13 REAG	CTOR RESERVE SHUTDOWN HOURS	0.0	0.0	2330.5
14 HOUR	S GENERATOR ON-LINE	701.7	5436.8	158283.6
15 UNII	RESERVE SHUTDOWN HOURS	0.0	0.0	10.0
16 GROS	S THERMAL ENERGY GENERATED (MWH)	1107004	8419145	250836487
17 GROS	S ELECTRICAL ENERGY GENERATED (MWH)	368200	2797200	83124200
18 NET	ELECTRICAL ENERGY GENERATED (MWH)	349617	2656078	79109578
19 UNII	SERVICE FACTOR	97.5	83.0	84.8
20 UNIT	AVAILABILITY FACTOR	97.5	83.0	84.8
21 UNIT	CAPACITY FACTOR (USING MDC NET)	95.0	79.3	82.7
22 UNIT	CAPACITY FACTOR (USING DER NET)	90.8	75.8	79.2
23 UNIT	FORCED OUTAGE RATE	2.5	0.3	2.0

²⁴ SHUTDOWNS SCHEDULED OVER NEXT 6 MONTHS (TYPE, DATE, AND DURATION OF EACH)
N/A

²⁵ IF SHUT DOWN AT END OF REPORT PERIOD, ESTIMATED DATE OF STARTUP - N/A