

50-331

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. James G. Keppler

FROM:

Iowa Electric Light & Power Co.
Cedar Rapids, Iowa
Me. Ellery L. Hammond

DATE OF DOCUMENT

2/11/77

DATE RECEIVED

2/23/77

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

☐ ORIGINAL☒ UNCLASSIFIED☒ COPY

NUMBER OF COPIES RECEIVED

One signed copy

DESCRIPTION

Ltr. trans the following:

**DO NOT REMOVE
ACKNOWLEDGED**

PLANT NAME:

(1-P)

Duane Arnold

ENCLOSURE

Licensee Event Report (RO 50-331/77-8) on
1/31/77 concerning the mounting bracket for
hydraulic shock suppressor HBB-25-SS-178 on
the fuel pool to RHR line being found to be
loose from the wall.....**NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS**

FOR ACTION/INFORMATION 2/23/77

RJL

☒

BRANCH CHIEF:

Lear

☒

W/3 CYS FOR ACTION

☒

LIC. ASST.:

Parrish

☒

W/ CYS

☒

ACRS 16 CYS HOLDING/SENT! (at 8. (2/23/77))

INTERNAL DISTRIBUTION

☒

REG FILE

☒

NRC PDR

☒

I & E (2)

☒

MIPC

☒

SCHROEDER/IPPOLITO

☒

HOUSTON

☒

NOVAK/CHECK

☒

GRIMES

☒

CASE

☒

BUTLER

☒

HANAUER

☒

TEDESCO/MACCARY

☒

EISENHUT

☒

BAER

☒

SHAO

☒

VOLLMER/BUNCH

☒

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

☒

LPDR: Cedar Rapids, Iowa

☒

TIC:

☒

NSIC:

CONTROL NUMBER

1858

R

W. Larkson

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER

P. O. Box 351

Cedar Rapids, Iowa 52406

February 11, 1977


DAEC - 77 - 105

REGULATORY DOCKET FILE COPY

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission-Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. 77
(14 day)

File: A-118a



Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Ellery L. Hammond

Ellery L. Hammond

Chief Engineer

Duane Arnold Energy Center


Docket 50-331

attachment

ELH/JVS/mg

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555



FEB 14 1977

1858

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME					LICENSE NUMBER								LICENSE TYPE					EVENT TYPE					
01	I	A	D	A	C	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9				14	15									25	26					31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE									
01	CON'T		T	L	0	5	0	-	0	3	3	1	0	1	3	1	7	7	0	2	1	1	7	7
7	8	57	58	59	60	61						68	69				74		75					80

EVENT DESCRIPTION

02	During inspection the mounting bracket for hydraulic shock suppressor	80
03	HBB-25-SS-178 on the fuel pool to RHR line was found to be loose from t	80
04	he wall. 1 concrete fastener was pulled loose from the wall and 3 mount	80
05	ing bolts were backed out slightly. The fastener was replaced and the m	80
06	ounting bolts tightened. (RO 77-8)	80

8 9 SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07 C F E H A N G E R A X 9 9 9 Y

7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08	Unknown. A nonconformance review has been initiated to investigate the	80
09	cause of the occurrence.	80
10		80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	8	3	NA		C	Special Inspection		
7	8	9	10	12	13	44	45	46	80	

FORM OF ACTIVITY RELEASED
1 2
7 8

CONTENT OF RELEASE
Z
9 10

AMOUNT OF ACTIVITY
NA
11 44

LOCATION OF RELEASE
NA
45 80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	NA

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	000		NA

OFFSITE CONSEQUENCES

[illegible]

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		NA

PUBLICITY

17	NA
7 8 9	

ADDITIONAL FACTORS

18	NA
7	8
9	

19	
7	8
9	

NAME: J. Van Sickel

PHONE: 319-851-5611