

DR Central

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
November 4, 1976
DAEC - 76 - 354

Mr. James G. Keppler, Director
Office of Inspection and Enforcement-Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Prompt Notification of a
Reportable Occurrence

50-331

File: A-118a

Dear Mr. Keppler:

This letter, telecopied to your office, is intended to satisfy the requirement for prompt notification of a Reportable Occurrence in accordance with Specification 6.11.2.a of the Duane Arnold Energy Center Technical Specifications.

Technical Specification paragraph(s) violated: N/A

Description Occurrence: Fire on diesel generator 1G-21 caused when a fitting on the fuel return line failed allowing fuel to spray out and be ignited by heat from the exhaust header. The diesel was immediately secured and the fire was extinguished.

Very truly yours,

G. G. Hunt / Bury

G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

GGH/DLW/mg

76-75

Director, Management Information and Program Control (2)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

104 File

NOV 8 1976