

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 2609

FILE: INCIDENT REPORT

FROM: Iowa Electric Light&Power Cedar Rapids, Iowa GG Hunt		DATE OF DOC 3-3-75	DATE REC'D 3-8-75	LTR XXXX	TWX	RPT	OTHER
TO: Mr Keppler		ORIG one signed	CC	OTHER	SENT AEC PDR <u>XX</u> SENT LOCAL PDR <u>XX</u>		
CLASS	UNCLASS XXXXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		

DESCRIPTION:

Ltr reporting Tech Specs deviation 75-2.....
failure to follow the Surveillance Test
Procedure for the period 2-1-75 thru 2-5-75
.....

ENCLOSURES:

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME: DUANE ARNOLD

FOR ACTION/INFORMATION 3-8-75 ehf

BUTLER (S) W/ Copies	SCHWENCER (S) W/ Copies	ZIEMANN (S) W/ Copies	REGAN (E) W/ Copies
CLARK (S) W/ Copies	STOLZ (S) W/ Copies	DICKER (E) W/ Copies	LEAR (S) W/4 Copies
FARR (S) W/ Copies	VASSALLO (S) W/ Copies	KNIGHTON (E) W/ Copies	SPEIS (S) W/ Copies
KNIEL (S) W/ Copies	PURPLE (S) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506-A GOSSICK /STAFF CASE GIAMBUSSO BOYD MOORE (S) (BWR) DEYOUNG (S) (PWR) SKOVHOLT (S) GOLLER (S) P. COLLINS DENISE REG OPR FILE & REGION T.R. WILSON	<u>TECH REVIEW</u> SCHROEDER MACCARRY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA STEELE VOLIMER	<u>DENTON</u> GRIMES GAMMILL ASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC. ASST.</u> DIGGS (S) GEARIN (S) GOULBOURNE (S) KREUTZER (E) LEE (S) MAIGRET (S) REED (E) SERVICE (S) SHEPPARD (S) SLATER (E) SMITH (S) TEETS (S) WILLIAMS (E) WILSON (S) INGRAM (S)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/input E. COUPE R. Hartfield (2) KLECKER F. WILLIAMS
---	---	---	---	--

EXTERNAL DISTRIBUTION


1-LOCAL PDR <u>Cedar Rapids, Ia</u> 1-TIC (ABERNATHY) 1-NSIC (BUCHANAN) 1-ASLB 1-NEWTON ANDERSON 5-ACRS SENT TO LIC. ASST. <u>Teets</u>	(1) (2) (10) -NATIONAL LABS 1-M. PENNINGTON, RM E-201 G.T. 1-CONSULTANTS NEWMARK/ELUME/AGBABIAN	1-PDR SAN/LA/NY 1-BROOKHAVEN NAT LAB 1-G. ULRIKSON, ORNL 1-AGMED (RUTH GUSSMAN) RM B-127 G.T. 1-J. RUNKLES, RM E-201 G.T.
--	--	---

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA
MARCH 3, 1975
DAEC-75-91

50-331



Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission, Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Technical Specification Violation 75-2
FILE: A-110
A-117

Dear Mr. Keppler:

This letter is to report to you a violation of a Technical Specification requirement at the Duane Arnold Energy Center.


Problem

The RBM level section of Surveillance Test Procedure (STP) No. 42A001 - Daily Instrument Checks was inadvertently not performed February 1, 1975 through February 5, 1975.

Investigation

In accordance with the requirements of STP 42A001, instrument checks are performed daily by Operations personnel. On the dates February 1, 1975 through February 5, 1975, the RBM level check portion of the STP was not performed. The checks were not performed because page 15 had inadvertently been omitted from the copy of the STP issued to Operations personnel.

Since the RBM level checks were satisfactory on January 31, 1975 and February 6, 1975, it has been concluded that the failure to perform the checks did not affect the safe operation of the plant during the six day period.



2609

3/3/75

Corrective Action

Personnel responsible for issuing copies of Surveillance Test Procedures have been made aware of this potential problem and have been reinstructed as to the importance of inspecting copies of Surveillance Test Procedures for completeness.

Conclusion

The DAEC Operations Committee reviewed and approved this report on March 3, 1975 and concluded that there was no hazard to the health and safety of the public.

Very truly yours,



G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

DLW:GGH:bh

CC: E. G. Case
C. W. Sandford
J. A. Wallace
E. L. Hammond
B. R. York
R. R. Rinderman
L. D. Root
H. W. Rehrauer-Chairman, Safety Committee
G. A. Cook
D. L. Wilson
J. V. Vinqvist
J. R. Newman
O. C. Schellberg
B. L. Hopkins