

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 1526

FILE: INCIDENT REPORT

FROM: Iowa Elec. Light & Power Co. Palo, Iowa G.C. Hunt		DATE OF DOC 2-5-75	DATE REC'D 2-10-75	LTR XX	TWX	RPT	OTHER XX
TO: Mr. J. Keppler		ORIG	CC 1	OTHER	SENT AEC PDR SENT LOCAL PDR		XX XX
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		

DESCRIPTION: Ltr reporting Abnormal Occurrence
AO-50-331/75-6 on 2-4-75 re inboard isolation
valve MOV-2700 did not close on signal...

ENCLOSURES:

ACKNOWLEDGED

Do Not Remove

PLANT NAME: Duane Arnold

FOR ACTION/INFORMATION DHL 2-11-75

BUTLER (S) W/ Copies	SCHWENCER (S) W/ Copies	ZIEMANN (S) W/ Copies	REGAN (E) W/ Copies
CLARK (S) W/ Copies	STOLZ (S) W/ Copies	DICKER (E) W/ Copies	LEAR (S) W/4 Copies
PARR (S) W/ Copies	VASSALLO (S) W/ Copies	KNIGHTON (E) W/ Copies	SPEIS (S) W/ Copies
KNIEL (S) W/ Copies	PURPLE (S) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> AEC PDR OGC, ROOM P-506-A GOSSICK /STAFF CASE GIAMBUSSO BOYD MOORE (S) (BWR) DEYOUNG (S) (FWR) SKOVHOLT (S) GOLLER (S) P. COLLINS DENISE REG_OPR FILE & REGION T.R. WILSON	<u>TECH REVIEW</u> SCHROEDER MACCARRY KNIGHT AWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLIMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC. ASST.</u> DIGGS (S) GEARIN (S) GOULBOURNE (S) KREUTZER (E) LEE (S) MAIGRET (S) REED (E) SERVICE (S) SHEPPARD (S) SLATER (E) SMITH (S) TEETS (S) WILLIAMS (E) WILSON (S) INGRAM (S)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/input E. COUPE R. Hartfield (2) KLECKER F. WILLIAMS
---	--	---	---	--

EXTERNAL DISTRIBUTION



1-LOCAL PDR Cedar Rapids, Iowa	(1)(2)(10)-NATIONAL LABS	1-PDR SAN/LA/NY
1-TIC (ABERNATHY)	1-W. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSON, ORNL
1-ASLB	NEWMARK/BLUME/AGBABIAN	1-AGMED (RUTH GUSSMAN) RM B-127 G.T.
1-NEWTON ANDERSON		1-J. RUNKLES, RM E-201 G.T.
5-ACRS SENT TO LIC. ASST. S. Teets 2-11-75		

Regulatory Docket File

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA
FEBRUARY 5, 1975
DAEC - 75 - 37



Mr. James Keppler, Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. AO-50-331/75-6
FILE: A-110 A-118a

Dear Mr. Keppler:

In accordance with DAEC Technical Specifications, Section 6.11.2A.1, this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on February 4, 1975. This letter, telecopied to your office, is intended to satisfy the requirements for notification by telegram within 24 hours of an abnormal occurrence.

Identification of Occurrence

Inoperable reactor water cleanup isolation valve, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and 3.7.D.1.

Description of Occurrence

During the performance of Surveillance Test No. 42A013 Reactor Water Cleanup Isolation Logic System Functional Test, it was determined that inboard isolation valve MOV-2700 did not close on signal.

Investigation is continuing.

A formal written report will be submitted to the Office of Inspection and Enforcement within 10 days of the subject abnormal occurrence.

Very truly yours,

G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

PDW:GGH:bh

- CC: ✓ E. G. Case
- C. W. Sandford
- J. A. Wallace
- B. R. York
- D. L. Wilson
- R. R. Rinderman
- L. D. Root
- G. A. Cook
- H. W. Rehrauer-Chairman, Safety Com.
- E. L. Hammond
- P. D. Ward
- B. L. Hopkins