IOWA ELECTRIC LIGHT AND POWER COMPANY

General Qffice Cedar Radids. Iowa Duane Arnold Energy Center PALO, Iowa October 18, 1974 DAEC - 74 - 362

Mr. James Keppler, Director Hegulatory Operations Regional Office U. S. Atomic Energy Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

> SUBJECT: Abnormal Occurrence No. DPR 50-331/74-42 FILE: A-118a A-110

Dear Mr. Keppler:

In accordance with the DAEC Technical Specifications, Section 6.11.2A.1, this letter is intended as notification of an abnormal occurrence at the Duane arnold Energy Center on October 18, 1974. This letter, telecopied to your office, is intended to satisfy the requirement for notification by telegram within 24 hours of the abnormal occurrence.

Identification of Occurrence

Suppression chamber level switch setting less conservative than the limiting setting established in the Technical Specifications, Section 3.2.B.

Description of Occurrence

Buring the conduct of Surveillance Test Procedure No. 42B020, Suppression Chamber High Water Level Instrument Functional Test, it was determined that the trip setting of level switch LS 2319 was 13 feet 3 3/8 inches. Considering it limit of 13 feet 2 3/4 inches and an instrument tolerance of $\pm 1/2$ inch, callowed by Technical Specification, paragraph 2, the setting should have been within 13 feet 2 1/4 inches to 13 feet 3 1/4 inches.

TA formal written report will be submitted to the Office of the Directorate of Regulatory Operations within 10 days of the subject abnormal occurrence.

Very truly yours, Classed CO)

G. G. Hunt Chief Engineer Duane Arnold Energy Center

DIN: GGH: bh CC: E. G. Case C. W. Sandford J. A. Wallace E. L. Hamsond

B. R. Maria

- D. L. Wilson
- L. D. Root
- B. W. Rehrauer, Chairman, and Song Coumittee B. L. Hopkins

4°6

10/18/74