## AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL (TEMPORARY FORM)

CONTROL NO. 11967

FII F		

FROM:	lowa Electr Cedar Rapid GG Hunt	ic Light&Powe s, Iowa	DATE OF DOC 11-19-74	DAT 11-23		LTR EX	TWX	RPT	OTHER FACSIMINALE
TO:	Mr Keppler		ORIG NONE SIGNED	CC	OTHER	SENT AEC PDRXXX SENT LOCAL PDRXXX			
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO C	YS REC'D 1	DOCKET NO: 50-331		•	
DECODIDE ON				ESICI	OCHEC.				

DESCRIPTION:

Ltr re abnormal occurrence #74-49 on 11-18-74 concerning main steam line high radiation trip settings which differed from the limits established in Tech Specs......

ENCLOSURES:

BUNGT REMOVE

PLANT NAME:

Duane Arnold

	F	OR ACTION INFORM	ATION 11-29-7	4 ehf
BUTLER (L)	SCHWENCER (L)	ZIEMANN (L)	REGAN (E)	
W. Copies	W/ Copies	W/ Copies	W/ Copies	-
CLARK (L)	STOLZ (L)	DICKER (E)	LEAR (L)	
W/ Copies	W/ Copies	W/ Copies	W/Copies	
PARR (L)	VASSALLO (L)	KNIGHTON (E)		
W/ Copies	W/ Copies	W/ Copies	W/ Copies	
KNIEL (L)	PURPLE (L)	YOUNGBLOOD (E)		
W/ Copies	W/ Copies	W/ Copies	W/ Copies	
		INTERNAL DISTRICT	TION	
REG FILE	TECH REMIEW	DEMTO!	LIC ASST	A/TIND
PAECPOR	P	GREGES		BRAIT
KASO, ROOM P-503A	€CHROEDER	GgwiiiiiHLL	DIGGS (L)	SALTZMAN
ÁGUNTZING/STAFF	JACCARY (%)	€NÄSTNER	GEARIN (L)	B. HURT
≶ĈASE	- ⊌KRIGHT	BALLARD	GOULBOURNE (L)	
GIAMBUSSO	€ AWLICKI	SPANGLER	KREUTZER (E)	<u>PLANS</u>
BOYD	<b>€</b> €HAO		LEE (L)	MCDONALD
MOORE (L) (EWR)	esi,ELLO	ENVIRO	MAIGRET (L)	CHAPMAN
DEYOUNG (L) (PWR)		MULLER	REED (E)	DUBE w.input
SKOVHOLT (L)	etigVAK	DICKER	SERVICE (L)	E. COUPE
GOLLER (L)	¢ଶ୍∂SS	KNIGHTON	SHEPPARD (L)	<u> 19</u>
P. COLLINS	<b>c</b> 4PPOLITO	YOUNGBLOOD	SLATER (E)	्रहर्द्द्र THOMPSON (३)
<b>DENISE</b>	TJRDESCO	REGAH	SMITH (L)	_ <b>&amp;</b> ₹ĠŁECKER
(BEGOPR	<b>€</b> CONG	PROJECT LDR 📗	TEETS (L)	<b>EISENHUT</b>
FILE & REGION (3)	<b>K</b> AINAS		WILLIAMS (E)	
MORRIS .	AYORAKEIN	HARLESS	WILSON (L)	

EXTERNAL DISTRIBUTION

LOCAL POR Water for

A. TIC (ADERICATION) -(1)(2)(10) = HATIQHAL LAPS

WOLLHER

🎻 - NSIC (BUCHANAM)

1 - ASLB

1 - Newton Amferson

t√STEELE

ିୟୁ ACRS HOLDING

Sent to Lic Asst. Teets

- ASLEP(E V. E. H., Roy 609) W. PERNER, B. D.L., Box 6-001/GT
- B&M SWENT PROAD, Rm E-201 GT CONSULT WITS
- 1 PDR SAN LAINY

- 1 BROOKHAVER NAT EAS
- 1 G. ULRIKSON, ORTIL
- 1 AGMED (NUTH GUAS Rm B-127 GT
- 1 -- R. D. MUELLER, P. SECT GT

# IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA

DUANE ARNOLD ENERGY CENTER
PALO, IOWA
NOVEMBER 19, 1974
DAEC - 74 - 395



C. Carea

Mr. James Keppler, Director
Regulatory Operations Regional Office
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. AO 50-331/74-49

FILE: A-118a A-110

### Dear Mr. Keppler:

In accordance with the DAEC Technical Specifications, Section 6.11.2A.1, this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on November 18, 1974. This letter, telecopied to your office, is intended to satisfy the requirements for notification by telegram within 24 hours of the abnormal occurrence.

## Identification of Occurrence

Main steam line high radiation trip settings, reportable in accordance with Appendix A, Operating License DPR-49, Specification 1.0.4.b , 3.1 and Table 3.1-1.

#### Description of Occurrence

On November 18, 1974, it was determined that the alarm and trip setpoints for the main steam line high radiation monitors were 3X and 6X normal rated power background levels respectively. In accordance with Table 3.1-1, the alarm and trip setpoints should have been 1.5X and 3X normal rated background levels respectively. The settings apparently were not readjusted on the first occasion reactor power reached 50 percent in accordance with note 14 to Table 3.1-1.

Investigation is continuing.

A formal written report will be submitted to the Office of Directorate of Regulatory Operations within 10 days of the subject abnormal occurrence.

Very truly yours,

G. G. Hunt Chief Engineer

Duane Arnold Energy Center

#### DLW:GGH:bh

CC: E. G. Case

C. W. Sandford

J. A. Wallace

E. L. Hammond

B. R. York

D. L. Wilson

R. R. Rinderman

L. D. Root

H. W. Rehrauer, Chairman, Safety Committee

G. A. Cook

B. L. Hopkins