

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 11101

FILE: _____

FROM: Iowa Electric Light & Power Cedar Rapids, Iowa CG Hunt		DATE OF DOC 10-22-74	DATE REC'D 10-29-74	LTR	TWX	RPT	OTHER FACSIMILE
TO: Mr. Keppler		ORIG NONE SIGNED	CC	OTHER	SENT AEC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		

DESCRIPTION:

Ltr re Abnormal occurrence #74-43 on 10-19-74
concerning intermediate range monitors

inoperable

ENCLOSURES:

DO NOT REMOVE

PLANT NAME: Duane Arnold

FOR ACTION INFORMATION

11-29-74 ehf

BUTLER (L)	SCHWENCER (L)	ZIEMANN (L)	REGAN (E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK (L)	STOLZ (L)	DICKER (E)	LEAR (L)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
PARR (L)	VASSALLO (L)	KNIGHTON (E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL (L)	PURPLE (L)	YOUNGBLOOD (E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC ASST</u>	<u>A/T IND</u>
<input checked="" type="checkbox"/> AEC PDR	<input checked="" type="checkbox"/> SCHROEDER	GRIMES	DIGGS (L)	BRAITMAN
<input checked="" type="checkbox"/> EGC, ROOM P-506A	<input checked="" type="checkbox"/> ACCARY	GAMMILL	GEARIN (L)	SALTZMAN
<input checked="" type="checkbox"/> MUNTZING/STAFF	<input checked="" type="checkbox"/> KNIGHT	KASTNER	GOULDSOURNE (L)	B. HURT
<input checked="" type="checkbox"/> CASE	<input checked="" type="checkbox"/> AWLICKI	BALLARD	KREUTZER (E)	<u>PLANS</u>
GIAMBUSO	<input checked="" type="checkbox"/> SHAO	SPANGLER	LEE (L)	MCDONALD
BOYD	<input checked="" type="checkbox"/> STELLO	<u>ENVIRO</u>	MAIGRET (L)	CHAPMAN
MOORE (L) (BWR)	<input checked="" type="checkbox"/> HOUSTON	MULLER	REED (E)	DUBE w/ input
DEYOUNG (L) (PWR)	<input checked="" type="checkbox"/> OVAK	DICKER	SERVICE (L)	E. COUPE
SKOVHOLT (L)	<input checked="" type="checkbox"/> ROSS	KNIGHTON	SHEPPARD (L)	
GOLLER (L)	<input checked="" type="checkbox"/> APOLITO	YOUNGBLOOD	SLATER (E)	<input checked="" type="checkbox"/> THOMPSON (2)
P. COLLINS	<input checked="" type="checkbox"/> TEDESCO	REGAN	SMITH (L)	<input checked="" type="checkbox"/> KLECKER
DENISE	<input checked="" type="checkbox"/> LONG	PROJECT LDR	TEETS (L)	<input checked="" type="checkbox"/> EISENHUT
<input checked="" type="checkbox"/> REG OPR	<input checked="" type="checkbox"/> MAINAS	<u>HARLESS</u>	WILLIAMS (E)	
<input checked="" type="checkbox"/> FILE & REGION (3)	<input checked="" type="checkbox"/> MENAROYA		WILSON (L)	
<input checked="" type="checkbox"/> MORRIS	<input checked="" type="checkbox"/> WOLIMER			
<input checked="" type="checkbox"/> STEELE				

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> LOCAL PDR <u>Cedar Rapids, IA.</u>	1 - PDR SAN/LA/NY
<input checked="" type="checkbox"/> TIC (ABERNATHY) (1)(2)(10) - NATIONAL LAPS	1 - BROOKHAVEN NAT LAB
<input checked="" type="checkbox"/> NSIC (DUCHANAN)	1 - G. ULRIKSON, ORNL
1 - ASLB	1 - AGMED (BETH GUSMAN)
1 - Newton Anderson	Rm B-127 GT
<input checked="" type="checkbox"/> ACRS HOLDING	1 - R. D. MUELLER, Rm E-201
Sent to Lic Asst. <u>Teets</u>	GT
1 - ASLSB (E.W. Saly, Rm 529)	
1 - W. PENNINGTON, Rm E-201 GT	
1 - B&M SWINEBROOK, Rm E-201 GT	
1 - CONSULTANTS	
NEW HAVEN BULL NEAGABADIAN	

REGULATORY DOCKET FILE COPY
IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA
OCTOBER 22, 1974
DAEC - 74 - 364



Mr. James Keppler, Director
Regulatory Operations Regional Office
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. DPR 50-331/74-43
FILE: A-118a A-110

Dear Mr. Keppler:

In accordance with DAEC Technical Specifications, Section 6.11.2A.1, this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on October 19, 1974. This letter, telecopied to your office, is intended to satisfy the requirement for notification by telegram within 24 hours of the identification of an abnormal occurrence.

Identification of Occurrence

Intermediate Range Monitors (IRM) inoperable, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and Table 3.1-1.

Description of Occurrence


While commencing a reactor startup following an inadvertent scram, it was determined that IRM instrument channels A and E (RPS Channel A) were inoperable. RPS Channel A was manually placed in the tripped condition and startup operations were suspended while the IRM's were repaired.

Investigation is continuing.

A formal written report will be submitted to the Office of Directorate of Regulatory Operations within 10 days of the identification of the subject abnormal occurrence.

Very truly yours,

G. G. Hunt
Chief Engineer
Duane Arnold Energy Center



DLW:GGH:bh

CC: E. G. Case B. R. York H. W. Rehrauer, Chairman, Safety Committee
C. W. Sandford D. L. Wilson G. A. Cook
J. A. Wallace R. R. Rinderman B. L. Hopkins
E. L. Hammond L. D. Root

11101