

REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT
NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO 9568-9608
 FILE: INCIDENT REPORT FILE

FROM: Iowa Electric Light & Power Palo. Iowa G.G. Hunt		DATE OF DOC 9-4-75	DATE REC'D 9-11-75	LTR	TWX	RPT XXX	OTHER
TO:		ORIG None	CC	OTHER		SENT AEC PDR XXX	XXX
CLASS		UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331	

DESCRIPTION:
 Letter trans the following.....

PLANT NAME: Duane Arnold

ENCLOSURES:
 Abnormal Occurrence # 75-47, on 9-4-75,
 Concerning Failure of Pressure differential
 indicating switch.....

(1 Copy Enclosure Received)

FOR ACTION/INFORMATION

SAB 9-15-75

- | | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)
W/ Copies | SCHWENCER (L)
W/ Copies | ZIEMANN (L)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (L)
W/ Copies | STOLZ (L)
W/ Copies | DICKER (E)
W/ Copies | LEAR (L)
W/ Copies |
| PARR (L)
W/ Copies | VASSALLO (L)
W/ Copies | KNIGHTON (E)
W/ Copies | SPELS
W/ Copies |
| KNIEL (L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | W/ Copies |

ACKNOWLEDGED
DO NOT REMOVE

INTERNAL DISTRIBUTION

- | | | | | |
|---|--|--|---|--|
| <u>REG FILE</u>
NRC PDR
OGC, ROOM P-506A
GOSSICK/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (L)
DEYOUNG (L)
SKOVHOLT (L)
GOLLER (L) (Ltr)
P. COLLINS
DENISE
REG OPR
FILE & REGION (2)
MIPC/PE (3)
STEELE | <u>TECH REVIEW</u>
SCHROEDER
MACCARY
KNIGHT
PAWLICKI
SHAO
**STELLO
**HOUSTON
**NOVAK
ROSS
IPPOLITO
TEDESCO
J. COLLINS
LAINAS
BENAROYA
VOLLMER | DENTON
**GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR
HARLESS | <u>LIC ASST</u>
R. DIGGS (L)
H. GEARIN (L)
E. GOULBOURNE (L)
P. KREUTZER (E)
J. LEE (L)
M. RUSHBROOK (L)
S. REED (E)
M. SERVICE (L)
S. SHEPPARD (L)
M. SLATER (E)
H. SMITH (L)
S. TEETS (L)
G. WILLIAMS (E)
V. WILSON (L)
R. INGRAM (L)
M. DUNCAN (E) | <u>A/T IND.</u>
BRAITMAN
SALTZMAN
MELTZ



<u>PLANS</u>
MCDONALD
CHAPMAN
DUBE (Ltr)
E. COUPE
PETERSON
HARTFIELD (2)
KLECKER
EISENHUT
WIGGINTON
F. WILLIAMS
HANAUER |
|---|--|--|---|--|

EXTERNAL DISTRIBUTION

- | | | |
|------------------------------------|--------------------------------|---|
| 1 - LOCAL PDR Cedar Rapids, Iowa | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT |
| 1 - Newton Anderson | | 1 - J. D. RUNKLES, Rm E-201
GT |
| 5 - ACRS SENT TO LIC ASST S. Teets | | |
| ** SEND ONLY TEN DAY REPORTS | | |

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office
 CEDAR RAPIDS, IOWA
 DUANE ARNOLD ENERGY CENTER
 PALO, IOWA
 SEPTEMBER 4, 1975
 DAEC-75-347



Mr. James G. Keppler
 Office of Inspection and Enforcement-Region III
 U. S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence 75-47
 FILE: A-110 A-118a

Dear Mr. Keppler:

In accordance with DAEC Technical Specifications, Specification 6.11.2.A.1, this letter is a notification of an abnormal occurrence at the Duane Arnold Energy Center on September 4, 1975. This letter, telecopied to your office, is intended to satisfy the requirement for notification by telegram within 24 hours of an abnormal occurrence.

Identification of Occurrence

Out-of-specification pressure differential indicating switch, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and Table 3.2.B..

Description of Occurrence

During the performance of Surveillance Test No. 42B025, HPCI Steam Line High Dp Instrument Functional Test/Calibration, it was determined that the trip setting of Pressure Differential Indicating Switch 2244 was 112.5 inches water. The limiting set point for operation is 100 ± 7 inches water. (See Abnormal Occurrence Report No. AO 50-331/74-47 submitted November 4, 1974.)

A formal written report will be submitted to the Office of Inspection and Enforcement within 10 days of the subject abnormal occurrence.

Very truly yours,

9658

G. G. Hunt
 Chief Engineer
 Duane Arnold Energy Center

DLW:GGH:pd

cc: (B. C. Rusche) L. D. Root R. R. Rinderman E. L. Hammond
 C. W. Sandford B. R. York G. A. Cook
 J. A. Wallace D. L. Wilson H. W. Rehrauer - Chairman, Safety Committee