

50-331

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

INCIDENT REPORT

TO: Mr Keppler

FROM: Iowa Elec Light & Pwr Co
Cedar Rapids, Ia
G G Hunt

4-13-76

4-16-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

none signed

DESCRIPTION

Ltr trans the following:

ENCLOSURE

Licensee Event #76-25 on 3-30-76 concerns binding of relay mechanism caused by out-of adjustment target reset mechanism.....

DO NOT REMOVE

ACKNOWLEDGED

PLANT NAME: Duane Arnold

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

4-19-76

ehf

BRANCH CHIEF:

Leah

W/3 CYS FOR ACTION

LIC. ASST:

Parrish

W/1 CYS

ACRS 6 CYS ~~HOLDING~~/SENT TO LA

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC (3)

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES/SCHWENCER

CASE

F. WILLIAMS

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Cedar Rapids, Ia

TIC

NSIC

CONTROL NUMBER

3864

REGULATORY DOCKET FILE COPY

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
April 13, 1976 - 105

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission-Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Subject: Licensee Event Report No. 76-25
(14 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,


G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

DLW/GGH/mg

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555



Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

3864

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION!)

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE				EVENT TYPE									
01	2	A	D	A	C	1	0	0	-	0	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9	14	15	25	26	30	31	32																
CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE											
01				T	L	0	5	0	-	0	3	3	1	0	3	3	0	7	6	0	4	1	3	7	6
7	8	57	58	59	60	61	68	69	74	75	80														

EVENT DESCRIPTION

02	During instrument AC undervoltage surveillance testing, relay 27-Y11																							80
03	did not trip when the supply fuses were pulled. The relay target reset																							80
04	mechanism was readjusted so that proper target operation could be at-																							80
05	tained. Westinghouse Type SV. R0 76-25																							80
06																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION		
07	E	B	F	R	E	L	A	Y	X	A	W	1	2	0	Y	
7	8	9	10	11	12	17	43	44	47	48						

CAUSE DESCRIPTION

08	Binding of relay mechanism caused by out-of-adjustment target reset																							80
09	mechanism. Cause for the out-of-adjustment target reset mechanism un-																							80
10	known.																							80

FACILITY STATUS		% POWER			OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
11	H	0	0	0	NA				B	Surveillance Testing				
7	8	9	10	12	13	44	45	46						
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE						
12	Z	Z	NA				NA							
7	8	9	10	11	44	45								

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION							
13	0	0	0	Z	NA						
7	8	9	11	12	13						

PERSONNEL INJURIES

NUMBER		DESCRIPTION								
14	0	0	0	NA						
7	8	9	11	12						

OFFSITE CONSEQUENCES

15	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																					
16	Z	NA																					
7	8	9	10																				

PUBLICITY

17	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: D. Wilson PHONE: 319-851-5611