

UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

August 11, 2011

APPLICANT: Energy Northwest

FACILITY: Columbia Generating Station

SUBJECT: SUMMARY OF TELEPHONE CONFERENCE CALL HELD ON

FEBRUARY 3, 2011, BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION AND ENERGY NORTHWEST, CONCERNING THE RESPONSES TO THE REQUEST FOR ADDITIONAL INFORMATION PERTAINING TO THE COLUMBIA GENERATING STATION, LICENSE

RENEWAL APPLICATION (TAC NO. ME3058)

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of Energy Northwest (the applicant), held a telephone conference call on February 3, 2011, to discuss and clarify the responses to the NRC's request for additional information (RAI) concerning the Columbia Generating Station, license renewal application.

Enclosure 1 provides a listing of the participants and Enclosure 2 contains a listing of the responses to the RAIs discussed with the applicant, including a brief description on the status of the items.

The applicant had an opportunity to comment on this summary.

Arthur D. Cunanan, Project Manager

Outhur Cunanar

Projects Branch 1

Division of License Renewal

Office of Nuclear Reactor Regulation

Docket No. 50-397

Enclosures: As stated

cc w/encls: Listserv

TELEPHONE CONFERENCE CALL COLUMBIA GENERATING STATION LICENSE RENEWAL APPLICATION LIST OF PARTICIPANTS February 3, 2011

PARTICIPANTS: AFFILIATIONS:

Arthur Cunanan U.S. Nuclear Regulatory Commission (NRC)

Abdul Sheikh NRC Christopher Sydnor NRC

John Twomey Energy Northwest (EN)

Marsha Eades EN
Douglas Ramey EN

TELEPHONE CONFERENCE CALL COLUMBIA GENERATING STATION LICENSE RENEWAL APPLICATIONS February 3, 2011

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of Energy Northwest, held telephone conference calls on February 3, 2011, to discuss the following responses to the request for additional information (RAI) concerning the Columbia Generating Station (CGS) license renewal application (LRA).

Response to follow up RAI B.2.35-2

Discussion: The staff discussed clarifying the inspection frequency of the Service Water (SW) spray header support.

The applicant clarified that the spray pond circular header supports in LRA Table 3.5.2-3, line items 4 and 5 is the SW spray header support and credits both the Structures Monitoring Program (SMP) and the Inservice Inspection Program-IWF (ISI-IWF) for the portions of the ring header above and below the water line. The portion above the water line is defined by the environment air-outdoor (line item 4) and the portion below the water line is defined by the environment raw water (line item 5). The applicant also clarified that the Spray pond circular header is treated as a single item (support) and both the above and below water line portions are inspected under ISI-IWF on a ten year frequency per the American Society of Mechanical Engineers Boiler and Pressure Vessel Code. The inspection of the above water line portion is performed by a qualified civil engineer on a four year frequency under the SMP and is credited in addition to the inspection performed under ISI-IWF.

The staff notes that other RAI responses submitted by the applicant require cross reference of the LRA and the RAI responses submitted on the docket in order to adequately answer the question.

The staff understands the applicant's response and no additional RAIs are required.

Response to RAI B.2.8-1 through RAI B.2.8-5

Discussion: The staff discussed Generic Letter 88-1 (GL 88-1) and inspection schedules for boiling water reactor (BWR) piping weldments, specifically the stainless steel recirculation system piping-to-valve weld 20RRC(6)-8 for the period of 1996 through 2001.

The applicant discussed following the requirements of GL 88-1. The applicant confirmed that it conducted an inspection of the 20RRC(6)-8 weld in 1996, resulting in no change in flaw size indicated, and therefore changed the weld category from Category F to Category E. Based on Category E schedule requirements in GL 88-01 (every two refueling cycles) the applicant conducted inspections of the subject weld in 1998 and 2001 with no indications of change. The applicant concluded in 2001 that the flaw was not due to intergranular stress corrosion cracking (IGSCC) and therefore was due to a fabrication defect. The applicant changed the weld category again from Category E to Category B the same year. The applicant continues to follow GL 88-01 requirements with an inspection of the subject weld scheduled for mid-2011.

The staff understands the applicant's response and no additional RAIs are required.

August 11, 2011

APPLICANT: Energy Northwest

FACILITY: Columbia Generating Station

SUBJECT: SUMMARY OF TELEPHONE CONFERENCE CALL HELD ON

FEBRUARY 3, 2011, BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION AND ENERGY NORTHWEST, CONCERNING THE RESPONSES TO THE REQUEST FOR ADDITIONAL INFORMATION PERTAINING TO THE COLUMBIA GENERATING STATION, LICENSE

RENEWAL APPLICATION (TAC NO. ME3058)

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of Energy Northwest (the applicant), held a telephone conference call on February 3, 2011, to discuss and clarify the responses to the NRC's request for additional information (RAI) concerning the Columbia Generating Station, license renewal application.

Enclosure 1 provides a listing of the participants and Enclosure 2 contains a listing of the responses to the RAIs discussed with the applicant, including a brief description on the status of the items.

The applicant had an opportunity to comment on this summary.

/RA/

Arthur D. Cunanan, Project Manager Projects Branch 1 Division of License Renewal Office of Nuclear Reactor Regulation

Docket No. 50-397

Enclosures: As stated

cc w/encls: Listserv

DISTRIBUTION:

See next page

ADAMS Accession No.: ML11220A010 *concurrence via e-mail

OFF	ICE	LA: DLR/RPB1*	PM: DLR/RPB1	BC: DLR/RPB1	LA: DLR/RPB1	PM: DLR/RPB1
NAN	ΛE	SFigueroa	ACunanan	DMorey	SFigueroa	ACunanan
DAT	E	08/08/2011	08/08/2011	08/11/2011	08/11/2011	08/11/2011

OFFICIAL RECORD COPY

Letter to Energy Northwest from Arthur D. Cunanan dated August 11, 2010.

SUBJECT: SUMMARY OF TELEPHONE CONFERENCE CALL HELD ON

FEBRUARY 3, 2011, BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION AND ENERGY NORTHWEST, CONCERNING THE RESPONSES TO THE REQUEST FOR ADDITIONAL INFORMATION PERTAINING TO THE COLUMBIA GENERATING STATION, LICENSE

RENEWAL APPLICATION (TAC NO. ME3058)

DISTRIBUTION:

HARD COPY:

DLR R/F

E-MAIL:

PUBLIC

RidsNrrDlr Resource RidsNrrDlrRpb1 Resource RidsNrrDlrRpb2 Resource RidsNrrDlrRarb Resource

RidsNrrDlrRapb Resource RidsNrrDlrRasb Resource

RidsNrrDlrRerb Resource

RidsNrrDlrRpob Resource

DDoyle BSingal WWalker, RIV RCohen, RIV LSubin, OGC