

50-331

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. James G. Keppler

FROM:

Iowa Electric Light & Pwr. Company
Cedar Rapids, Iowa
Ellery L. Hammond

DATE OF DOCUMENT

5/24/77

DATE RECEIVED

6/8/77

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☒ ORIGINAL
☐ COPY☐ UNCLASSIFIED

1 SIGNED

DESCRIPTION

ENCLOSURE

Licensee Event Report (RO 50-331/77-37) on
5/10/77 concerning 1G-21 standby diesel
generator not supplying power to Bus 1A4
when required.....

PLANT NAME:

Duane Arnold

(1-P)

RJL

DO NOT REMOVE(1-P) **ACKNOWLEDGED**NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:

LEAR

W/3 CYS FOR ACTION

LIC. ASST.:

PARRISH

W/ / CYS

ACRS 16 CYS HOLDING/SENT

AS CAT B

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: CEDAR RAPIDS 1A.

TIC:

NSIC:

771590268

A4

60

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406

May 24, 1977
DAEC-77 -287

Regulatory Docket File



Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission-Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. 77-37
(14 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Ellery L. Hammond

Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

ELH/JVS/mg

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

MAY 27 1977

771590268

(PLEASE PRINT ALL REQUIRED INFORMATION)

EVENT DESCRIPTION

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
E	E	E	C	K	T	B	R	K	N	G	O	8	O	Y
10	11		12				17	43	44			47	48	

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
H			0 0 0			NA			B			Surveillance Test		
9			10 11 12			13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43			44 45			46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99		

PERSONNEL EXPOSURES

PERSONNEL INJURIES

OFFSITE CONSEQUENCES

LOSS OR DAMAGE TO FACILITY

PUBLICITY

ADDITIONAL FACTORS

19 | problems noted. No further corrective action planned.

GPO 881-667

RECEIVED DOCUMENT
PROCESSING UNIT

1971 JUN 7 AM 10 37