

50-331

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO: Mr. James G. Keppler

FROM: Iowa Electric Light & Pwr. Company Cedar Rapids, Iowa Ellery L. Hammond

DATE OF DOCUMENT

6/23/77

DATE RECEIVED

7/13/77

LETTER ORIGINAL COPY

NOTORIZED UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 SIGNED

DESCRIPTION

ENCLOSURE

Licensee Event Report (RO 50-331/77-47) on 5/31/77 concerning the surveillance test procedure requiring APRM high flux & inoperative instrument calibration not being completed within the required time frame....

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME:

Duane Arnold

RJL 7/13/77

(1-P)

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF: W/ 3 CYS FOR ACTION LIC ASST.:

Leav Parish

INTERNAL DISTRIBUTION

- REG FILE NRC PDR I & E (2) MIPC SCHROEDER/IPPOLITO HOUSTON NOVAK/CHECK GRIMES KNIGHT BUTLER HANAUER TEDESCO EISENHUT RAER SHAO VOLLMER/BUNCH KREGER/ J. COLLINS ROSA

EXTERNAL DISTRIBUTION

LPDR: Cedar Rapids Ia TIC: NSIC: ACRS (16) SENT AS CAT. B

CONTROL NUMBER

AD 4

771940216

D. Lantieri

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406

June 23, 1977
DAEC-77 - 343


Regulatory

File Cys

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission - Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. 77-47
(30 day)

File: A-118a



Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Ellery L. Hammond

Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

ELH/JVS/mg

cc: Director, Office of Inspection and Enforcement (30)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

771940216

JUN 27 1977

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	I	A	D	A	C	1
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	3
---	---

CONT:

01

 CATEGORY:

--	--

 REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	3	3	1
---	---	---	---	---	---	---	---

 EVENT DATE:

0	5	3	1	7	7
---	---	---	---	---	---

 REPORT DATE:

0	6	2	3	7	7
---	---	---	---	---	---

EVENT DESCRIPTION

02 | Surveillance Test Procedure requiring APRM high flux and inoperative in
7 8 9 | strument calibration was not completed within the required time frame. | 80
03 |
7 8 9 | The Surveillance Test was to have been completed by 5/18/77 and was act | 80
04 |
7 8 9 | ually completed on 5/31/77. (RO 77-47) | 80
05 |
7 8 9 | | 80
06 |
7 8 9 | | 80

SYSTEM CODE:

Z	Z
---	---

 CAUSE CODE:

A

 COMPONENT CODE:

Z	Z	Z	Z	Z	Z
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

Z

 COMPONENT MANUFACTURER:

Z	9	9	9
---	---	---	---

 VIOLATION:

Y

CAUSE DESCRIPTION

08 | The STP was not accomplished when initially scheduled due to the plant
7 8 9 | being shutdown for refueling. The test was not rescheduled and complete | 80
09 |
7 8 9 | d within the required time frame due to personnel oversight. The person | 80
10 |
7 8 9 | | 80

FACILITY STATUS:

E

 % PDWER:

0	8	7
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

B

 DISCOVERY DESCRIPTION:

Routine Inspection

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

13 | NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

14 | NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

OFFSITE CONSEQUENCES

15 |

NA

LOSS OR DAMAGE TO FACILITY

16 | TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

17 |

NA

ADDITIONAL FACTORS

18 | Cause Desc. Cont. - nel involved will be reinstructed as to the
7 8 9 | importance of properly scheduling surveillance tests. | 80
19 |
7 8 9 | | 80

NAME: J. Van Sichel PHONE: 319-851-5611