

SEP 19 1977

Docket No. 50-331

Iowa Electric Light and Power Company
ATTN: Mr. Duane Arnold
President
IE Tower
P. O. Box 351
Cedar Rapids, IA 52406

Gentlemen:

Thank you for your letter dated August 25, 1977, informing us of the steps you have taken to correct the noncompliance identified in our letter dated August 3, 1977. We have reviewed your response and note that your corrective action includes a review to determine what changes may be needed to ensure that Control Room controlled drawings are maintained up-to-date. This review is to be completed by October 1, 1977. Upon completion of the above review it is requested that you inform this office of the results of this review including any additional corrective action you have deemed necessary.

Your cooperation with us is appreciated.

Sincerely,

Gaston Fiorelli, Chief
Reactor Operations and
Nuclear Support Branch

cc: Mr. J. A. Wallace, Vice
President-Generation
Mr. E. L. Hammond, Chief
Engineer

cc w/ltr dtd 8/25/77:
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC

69

OFFICE	RIII <i>ret</i>	RIII <i>ret</i>	RIII	RIII XXXX	RIII	
SURNAME	Kister/ <i>ls</i>	Knop	Fiorelli <i>ls</i>	Nokelius	Keppler	
DATE	9/16/77				<i>ls</i>	

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office
CEDAR RAPIDS, IOWA

JAMES A. WALLACE
VICE PRESIDENT - GENERATION

August 25, 1977

Mr. James G. Keppler, Director
Office of Inspection and Enforcement, Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

RE: Duane Arnold Energy Center
SUBJECT: Response to Letter from Gaston
Fiorelli to Duane Arnold dated
August 3, 1977
FILE: A-102 Inspection Report 77-15

Dear Mr. Keppler:

This letter is in response to Mr. Fiorelli's letter concerning an inspection of activities at the Duane Arnold Energy Center conducted on June 1, 27-30; July 1, and 11-14, 1977. The following responses indicate the actions which have been or will be taken to correct the items of noncompliance identified in Mr. Fiorelli's letter.

Infraction

Contrary to 10 CFR, Part 50, Appendix B, Criterion XVI and Quality Assurance Directive QAD 1316.1, paragraph 5.1, the licensee failed to take adequate corrective action to ensure that controlled drawings are maintained up-to-date in accordance with DAEC Quality Assurance Directives and Administrative Control Procedures.

Response

1. Corrective action taken and the results achieved:

The Control Room drawings identified by the Inspector as not being up to date were replaced with copies of the most current revision. This action was completed the same day this problem was identified by the Inspector.

AUG 29 1977

2. Corrective action to be taken to avoid further noncompliance:

Administrative priorities will be reviewed with the intent of determining what changes may be needed to ensure that Control Room controlled drawings are maintained up-to-date. Currently a complete new set of the most recent revision of controlled drawings required by the Control Room is being assembled.

3. Date when full compliance will be achieved:

The Administrative priorities review will be completed by October 1, 1977. The new set of up-to-date controlled drawings will be available in the Control Room by September 15, 1977.

Very truly yours,

J. A. Wallace ELH

J. A. Wallace
Vice President-Generation

JAW/JVS/ab

cc: Director, Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555