FACIL:50 AUTH.N/ LIU,L. RECIP.N	IA ELEC LIGHT & PWR	RIC & POWER CO.	DOCKET # 05000331
SUBJECT	Forwards rept"Duane Arnold En Safe End Repair Prog.781208" Replacement design stress rep See rep JTION CODE: A001S COPIES RECE	nergy Ctr Recirculation Inlet suppl rept submitted 780731. pt ençl.	
NOTES:			
ACTION:	RECIPIENTCOPIESID CODE/NAMELTTR ENCL05 BC ORB#37	RECIPIENT COPIES ID CODE/NAME LTTR ENCL	
16	REG FILE 1 12 I&E 2 +5 CORE PERF BR 1 +7 ENGR BR 1 +9 PLANT SYS BR 1	O2NRCPDR1114HANAUER115+0ADSYS/PROJ11+8REACSFTYBR120EEB11	•
EXTERNAL:	21 EFLT TRT SYS 1 1 03 LPDR 1 1 23 ACRS 16 16	O4 NSIC I I	
			~ ``.
.			
		DEC 14 1970	

REGULATORY DOCKET FILE COPY

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office Cedar Rapids, Iowa

December 8, 1978 IE-78-1782

LEE LIU SENIOR VICE PRESIDENT - ENGINEERING

Mr. Harold Denton, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Denton:

Enclosed is a report titled "Duane Arnold Energy Center Recirculation Inlet Safe End Repair Program, December 8, 1978" which supplements our report submitted July 31, 1978. Also enclosed is the replacement design stress report prepared by CBI Nuclear Company.

If you have any questions, please feel free to call us.

Very truly yours,

M. K. Kraus

Lee Liu Senior Vice President - Engineering

LL/KAM/CC

Enclosures (1 and 2)

CC: All w/enclosure 1 only K. Meyer

D. Arnold

R. Lowenstein

- H. Rehrauer
- File B-31c D. Clark (NRC)

A001 5 40/40 55-335

