

Central Files

Iowa Electric Light and Power Company

July 15, 1980
DAEC - 80 - 331

Mr. James G. Keppler, Director
Office of Inspection and Enforcement-Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Re: Duane Arnold Energy Center
Subject: 1980 Local Leak Rate Tests
File: A-110

Dear Mr. Keppler:

Please find enclosed for your review copies of the Local Leak Rate Test report for Type B and C tests conducted at the DAEC during the 1980 refueling outage.

Very truly yours,

Daniel L. Mineck

Daniel L. Mineck
Chief Engineer
Duane Arnold Energy Center

DLM/JVS/rs

Enclosures

cc: NRC Resident Inspector-DAEC

8007230482

JUL 17 1980
MA
60

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8007230482 DOC. DATE: 80/07/15 NOTARIZED: NO DOCKET #
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH. NAME AUTHOR AFFILIATION
 MINECK, D.L. Iowa Electric Light & Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 KEPPLER, J.G. Region 3, Chicago, Office of the Director

SUBJECT: Forwards rept, "Reactor Containment Local Leakage Rate Testing, 1980 Outage."

(see 8007220394 - same report sent to Denton)

DISTRIBUTION CODE: A017S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+21
 TITLE: Containment Leak Rate Testing - Appendix J

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	IPPOLITO, T. 05	1 1	KEVERN, T.	1 1
INTERNAL:	A/D CORE & CS	1 0	CONT SYS BR 22	1 1
	D/DIR, HUM FAC S	1 0	I&E 12	2 2
	NRC PDR 02	1 1	OELD 21	1 1
	OR ASSESS BR 18	1 1	PROC/TST REV BR	1 1
	REG FILE 01	1 1		
EXTERNAL:	ACRS 24	16 16	LPDR 03	1 1
	NSIC 04	1 1		

JUL 24 1980

MD
2

GP

TOTAL NUMBER OF COPIES REQUIRED: LTR 30 ENCL 28

Iowa Electric Light and Power Company

July 15, 1980
DAEC - 80 - 331

Mr. James G. Keppler, Director
Office of Inspection and Enforcement-Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Re: Duane Arnold Energy Center
Subject: 1980 Local Leak Rate Tests
File: A-110

Dear Mr. Keppler:

Please find enclosed for your review copies of the Local Leak Rate Test report for Type B and C tests conducted at the DAEC during the 1980 refueling outage.

Very truly yours,

Daniel L. Mineck

Daniel L. Mineck
Chief Engineer
Duane Arnold Energy Center

DLM/JVS/rs

Enclosures

cc: NRC Resident Inspector-DAEC

A017
S. 11

8007230462