

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8212090337 DOC. DATE: 82/12/03 NOTARIZED: NO DOCKET #
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH. NAME AUTHOR AFFILIATION
 ROOT, L.D. Iowa Electric Light & Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director

SUBJECT: Submits info on emergency operations facility (EOF) per
 F Apicella request. EOF established in tower at util
 corporate ofcs located more than 10 miles from facility per
 NUREG-0696.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES:

RECIPIENT			COPIES		RECIPIENT			COPIES	
ID CODE/NAME			LTTR	ENCL	ID CODE/NAME			LTTR	ENCL
NRR ORB2 BC 01			7	7					
INTERNAL: ELD/HDS2			1	0	NRR/DL DIR			1	1
NRR/DL/ORAB			1	0	NRR/DSI/RAB			1	1
<u>REG FILE</u> 04			1	1	RGN3			1	1
EXTERNAL: ACRS 09			6	6	LPDR 03			1	1
NRC PDR 02			1	1	NSIC 05			1	1
NTIS			1	1					

Iowa Electric Light and Power Company

December 3, 1982
NG-82-2717

LARRY D. ROOT
ASSISTANT VICE PRESIDENT
NUCLEAR GENERATION

Mr. Harold Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Denton:

During a phone conversation between Mr. F. Apicella of your staff, and Mr. R. Salmon of Iowa Electric, Mr. Apicella requested the following information, with regard to Iowa Electric's Emergency Operations Facility (EOF): location, type of structure, date building started, construction status, protection factor, and the need for high efficiency particulate absolute (HEPA) filters.

As stated in Iowa Electric's letter, LDR-80-120, dated May 1, 1980, and as confirmed in NRC Inspection Report 50-331/81-03 the EOF has been established at the Company's Corporate Offices in the ie: Tower, which is located slightly more than ten miles southeast of the DAEC site. The ie: Tower is a well engineered building constructed primarily of steel, concrete, and glass. Construction of this building was completed in the early 1970's. As the ie: Tower is located at a distance greater than 10 miles from DAEC, per NUREG-0696, no protection factors or special ventilation systems are required. Further adequacy of this facility has been successfully demonstrated during recent exercises which have included both NRC observation and participation.

If you have any additional questions regarding this matter, please contact Mr. Randy Portz, Emergency Planning Assistant at 319-398-8174.

Very truly yours,

Larry D. Root

Larry D. Root
Assistant Vice President
Nuclear Generation

A001

8212090337 821203
PDR ADOCK 05000331
F PDR

LDR/RP/rh*

cc: R. Portz
D. Arnold
L. Liu
S. Tuthill

F. Apicella (NRC)
NRC Resident Office
File A-221

* 1882 - A CENTURY OF SERVICE - 1982 *