



Fisher Controls International LLC  
301 South First Ave  
P.O. Box 190  
Marshalltown, Iowa 50158-0190  
USA  
T (641) 754-3011  
F (641) 754-2830

August 3, 2011

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555-0001

Subject: Possible Weld Rod Certification Issues Interim Notification

Fisher Controls is providing this interim notification per the requirements of 10CFR21.21(a).

On March 3, 2011, an audit of one of Fisher Control's suppliers determined that weld rod certified by an ISO process (instead of ASME) might have been used for weld repair of castings intended for nuclear service. Fisher and the supplier are in the process of reviewing all orders affected by this issue and have yet to find any that used the subject non-conforming material.

Fisher expects to complete this evaluation by August 26, 2011. At that time, if the review determines that a failure to comply condition exists, Fisher will issue a notification per the requirements of 10CFR21.21(b).

A handwritten signature in black ink, appearing to read 'Bill Fitzgerald', written over a horizontal line.

Bill Fitzgerald  
Vice President, Nuclear Business Unit  
Emerson Process Management, Fisher Valve Division



IE20