

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH: August 1988

Docket No.: 050-0331
 Unit: Duane Arnold Energy Center
 Date: 10-15-88
 Completed By: Lonnie Miller
 Telephone: (319) 851-7204

No.	Date	Type(1)	Duration (Hours)	Reason(2)	Method of Shutting (3) Down Reactor	Licensee Event Report #	System Code (4)	Comp. Code (5)	Cause
1	08-26-88	S	42.5	B	2	N/A	N/A	N/A	The reactor was taken off line to perform maintenance on a primary containment isolation valve. The cause of the improper operation of the valve was determined to be due to dirt on one of the contacts of the limit switch. A new limit switch was installed.

1 - F: Forced
 S: Scheduled

2 - Reason:
 A-Equipment Failure (Explain)
 B-Maintenance or Test
 C-Refueling
 D-Regulatory Restriction
 E-Operator Training & License Examination
 F-Administrative
 G-Operational Error (Explain)
 H-Other (Explain)

3 - Method
 1-Manual
 2-Manual Scram
 3-Automatic Scram
 4-Continued
 5-Reduced Load
 9-Other (Explain)

4 - Exhibit G-
 Instructions for
 Preparation of Data
 Entry Sheets for
 Licensee Event Report
 (LER) File (NUREG-
 0161)

5 - Exhibit 1-
 Same Source

(9/77)

8811010345 881015
 PDR ADOCK 05000331
 R PDR