# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

DOC.DATE: 91/02/28 NOTARIZED: NO ACCESSION NBR:9104100086 DOCKET # FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331 AUTHOR AFFILIATION AUTH.NAME TRAN, H. Iowa Electric Light & Power Co. WILSON, D.L. Iowa Electric Light & Power Co. RECIP. NAME RECIPIENT AFFILIATION R DAVIS, A.B. Region 3 (Post 820201) SUBJECT: Monthly operating rept for Feb 1991 for Duane Arnold Energy D Ctr.W/910311 ltr. DISTRIBUTION CODE: IE24D COPIES RECEIVED:LTR ENCL / TITLE: Monthly Operating Report (per Tech Specs) NOTES: RECIPIENT COPIES RECIPIENT COPIES LTTR ENCL ID CODE/NAME ID CODE/NAME LTTR ENCL D PD3-3 LA 3 3 PD3-3 PD 1 HALL, J.R. 1 1 D INTERNAL: ACRS 10 10 AEOD/DOA 1 1 S AEOD/DSP/TPAB NRR/DLPQ/LPEB10 1 1 1 1 NRR/DOEA/OEAB 1 1 REG. FILE 1 RGN3 1 1 EXTERNAL: EG&G BRYCE, J. H NRC PDR 1 1 1 1

NOTE TO ALL "RIDS" RECIPIENTS:

NSIC

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

R

D

S

Α

D

D

S

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

1

1

# Iowa Electric Light and Power Company

March 11, 1991 DAEC-91-0184

Mr. A. Bert Davis Regional Administrator Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Subject:

Duane Arnold Energy Center Docket No: 50-331

Op. License DPR-49 February 1991 Monthly Operating Report

Dear Sirs:

Please find enclosed the Duane Arnold Energy Center Monthly Operating Report for February 1991. The report has been prepared in accordance with the guidelines of NUREG-0020 and distribution has been made in accordance with DAEC Technical Specifications, Section 6.11.1.c.

Very traly yours,

David L. Wilson

Plant Superintendent - Nuclear

DLW/ht/pwj Enclosures File A-118d

Dir. of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Mail Station P1-137 Washington, D. C. 20555

Mr. S. P. Sands Project Manager 1 Whiteflint North Mail Stop 13E21 11555 Rockville Pike Rockville, MD 20852

INPO Records Center 1100 Circle 75 Parkway Suite 1500 Atlanta, GA 30339-3064

Mr. Steve Brown Iowa State Utilities Board Lucas State Office Building Des Moines, IA 50319

Mr. Fred Yost Director, Research Services Utility Data Institute 1700 K St. NW, Suite 400 Washington, DC 20006

Mr. William Loveless U. S. NRC 1 Whiteflint North Mail Stop 11C14 11555 Rockville Pike Rockville, MD 20852 (2)

NRC Resident Inspector

Mr. Dennis Murdock Central Iowa Power Cooperative Box 2517 Cedar Rapids, IA 52406

Mr. Dale Aherns Corn Belt Power Cooperative 1300 13th Street North Humboldt, IA 50548

Dr. William R. Jacobs, Jr. GDS Associates, Inc. Suite 720 1850 Parkway Place Marietta, GA 30068-8237

## OPERATING DATA REPORT

والمرابع والمتعافظة والمتراوين والمتراوين والمتراوية والمتراوية والمتعاولة وا

DOCKET NO. 050-0331
DATE 03-15-91
COMPLETED BY Hai Tran
TELEPHONE (319) 851-7491

OPERATING STATUS	Notes	Notes			
1. Unit Name: <u>Duane Arnold Energy Center</u> 2. Reporting Period: <u>February 1991</u> 3. Licensed Thermal Power (MWt): <u>1658</u> 4. Nameplata Rating (Gross MWe): <u>565 (Turbin</u> 5. Design Electrical Rating (Not MWe): <u>538</u> 6. Maximum Dependable Capacity (Gross MWe):  7. Maximum Dependable Capacity (Not MWe): <u>53</u> 8. If Changes Occur in Capacity Ratings (Item the Last Report, Give Reasons: <u>N/A</u>	565 58 ss Number 3 thr	rough 7) Since			
9. Power Lsvel to Which Rastricted, If Any (N 18. Reasons for Restrictions, If Any: N/A			Cumulative		
11. Hours in Reporting Period	672.0	1416.0	140928.0		
12. Number of Hours Reactor Was Critical	579.2	1141.6	101652.4		
13. Reactor Reserve Shutdown Hours	. 0	. 0_	192.8		
14. Hours Generator On-Line	569.3	1088.8	98797.0		
15. Unit Reserve Shutdown Hours	.0	.0			
16. Gross Thermal Energy Generated (HWH)	896508.0	1730637.6	131451871.6		
17. Gross Electrical Energy Generated (HWN)	299869.0	578644.0	44132535.0		
18. Net Electrical Energy Generated (HWN)	280983,7	541275.2	41358976.4		
19. Unit Service Factor	84,7	76.9	70.1		
20. Unit Availability Fector	84.7	76.9	70.2		
21. Unit Capacity Factor (Using MDC Net)	77.7_	71.1	56.5		
22. Unit Capacity Factor (Using DER Net)	77.7	71.1	54.5		
23. Unit Forced Outage Rate	15.3	12.2	13.8		
24. Shutdowns Scheduled Over Haxt 6 Honths (1 of each: N/A	Type, Date, and	d Duration			
25. If Shutdown at Eod of Report Period, Est	. Data of Ster	tup: <u>N/A</u>		<del></del>	

(9/77)

## AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 050-0331

DATE 03-15-91

COMPLETED BY Hai Tran

TELEPHONE (319) 851-7491

			•
HONTH	February 1991		
DAY	AVERAGE DAILY POWER LEVEL	DAY	AVERAGE DAILY POWER LEVEL
	(HWa-Nat)		(MWe-Not)
1	518.0	16	486.0
2	521.0	17	494.0
3	495.0	18	507.0
4	514.0	19	507.0
5	527.0	20	508.0
6	527 0	21	504.0
7	596.0	22	508.0
8	527.0	23	507.0
9	365.0	24	477.0
10	0.0	25	506.0
11	0.0	26	504.0
12	0,0	27	504.0
13	0.0	28	501.0
14	290.0	29	N/A
15	441.0	30	N/A
	<b>\</b>	31	N/A

REFUELING INFORMATION

DOCKET NO. 50-0331

DATE 03-15-91

COMPLETED BY Hai Tran
TELEPHONE (319) 851-7491

- 1. Name of facility.
  - a. Duane Arnold Energy Center
- 2. Scheduled data for next rofueling shutdown.
  - a. March I, 1992
- 3. Scheduled date for restart following refueling.
  - a. May 1, 1992
- 4. Will refueling or resumption of operation thereafter require a technical specification change or other license amendment?

N/A

 Scheduled date(s) for submitting proposed licensing action and supporting information.

N/A

 Important liconsing considerations associated with refueling, e.g., new or different fuel design or sumplier, unreviewed design or performance analysis methods, significant changes in fuel design, new operating procedures.

N/A

- The number of fuel assemblies (a) in the core and (b) in the spent fuel storage pool.
  - a. 368 b. 1048
- The present licensed spent fuel pool storage capacity and the size of any increase in licensed storage capacity that has been requested or is planned, in number of fuel assemblios.
  - a. 2050 Liconsed Capacity or
     b. 1898 under the presently installed storage rack capacity.
- The projected date of the last refueling that can be discharged to the spent fuel pool assuming the present licensed capacity.
  - a. 2000 Licensed Capacity or b. 1997 under the presently installed storage rack capacity.

# UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH: February 1991

Docket No.: 050-0331

Unit: Duane Arnold Energy Center

Date: 03-15-91

Completed By: Hai Tran

Telephone: (319) 851-7491

No.	Date	Туре(1) 		Reason(2)	Method of Shutting (3) Down Reactor	Licensee Event Report #	System Code (4)	Comp. Code (5)	Cause
	02-U9-9 <u>1</u>	<b> -</b>	102.7	<b>H</b>	3	91-003	N/A	N/A	While operating at full power, a reactor scram occurred due to a sensed low control oil prassure at the Main Turbine Control valves. Troubleshooting identified induced electrical noise in the Turbine Elector-Hydraulic Control (EHC) System, which appeared to have caused the pressure fluctuation in EHC control oil.
			,				·		
							·		,

I - F: Forced S: Scheduled

2 - Reason:

A-Equipment Failure (Explain)

B-Maintenance or Test

C-Refueling

D-Regulatory Restriction

E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain)

H-Other (Explain)

3 - Method

1-Manual

2-Manual Scram

3-Automatic Scram

4-Continued

5-Reduced Load

9-Other (Explain)

4 - Exhibit G-Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

5 - Exhibit 1-Same Source

## MAJOR/SAFETY RELATED MAINTENANCE

Docket No.: 050-0331
Unit: Duane Arnold Energy Center 03-15-91
Completed By: Hai Tran
Telephone: (319) 851-7491

DATE	SYSTEM	COMPONENT	DESCRIPTION
02-07-91	'B' Residual Heat Removal (RHR) System	Limitorque Operators	The limitorque operators of various 'B' pump suction valvas were overhauled. Two current ammaters for tha RHR pump motors were inspacted and calibrated. Also, oil samples were taken from the pump motors for analysis.
02-09-91	Turbine Electro-Hydraulic Control (EHC) System	Speed Error Circuitry	The speed error circuitry was found out of adjustment and readjusted, also the circuit cables ware shielded to eliminate potential noise sources. The mechanical overspeed limit switch of the EHC system was found sticky and racalibrated.
02-15-91	'B' Emergency Diesel Generator	Lube Oil Temperature Indicator	The lube oil temperature indicator was found indicating inaccurately and readjusted. The lube oil temperature was verified within the specified temperature range.
			and readjusted. The lube oil tempe was verified within the specified

#### NARRATIVE SUMMARY OF OPERATING EXPERIENCE

DOCKET NO. 050-0331
DATE 03-15-91
COMPLETED BY Hai Tran
TELEPHONE (319) 851-7491

- 02-01-91. The plant was operating at 99.7% of rated thermal power delivering 518.0 MWe to the grid. There was one 10 CFR 50.73 reportable event during the month.
- At 1659 hours, a reactor scram from 100% power occurred due to a sensed low control oil pressure at the Main Turbine Control valves. Extansive troubleshooting following tha event idantified induced electrical noise in the Turbine Electro-Hydraulic (EHC) System which appeared to have ultimately caused the pressura fluctuation in EHC control oil. Corrective actions were to eliminate potantial noise sources identified during troubleshooting. All automatic actions occurred as designed as a result of the scram. Operator actions were appropriate and expeditiously returned the plant to a stable condition.

#### LER 91-003

- 02-13-91 At 0955 hours, reactor startup commenced. The reactor was taken to critical at 1350 hours. The generator was synchronized to the grid at 2342 hours.
- 02-17-91 Reactor power was limited to 97% due to potantial drifing of the feedwater flow transmitter. This limitation will remain in effect until the transmitters are replaced.
- 01-28-91 At the ond of the month the plant was operating at 96.6% of rated thermal power delivering 501.0 MWe to the grid.