NRC FORM 591M PART (4-2008)	1			U.S. NUCLEAR	REGULATORY COMMISSION
10 CFR 2.201	SAFETY INS	PECTION REPORT	AND COMPLIANC	E INSPECTIO	
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
Alaska Heart Institute, LLC 3841 Piper Street, Suite 100 Anchorage, Alaska 99508 Location: 3841 Piper St. Anchorage, Alaska, REPORT NO: 2011-001			U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125		
3. DOCKET NUMBER	.011-001	4. LICENSE NUMBER		5 DATE OF	INSPECTION
		50-29111-01	1		, 2011
LICENSEE:					
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
	l iconsoo'	s Statement of Cor	ractive Actions for	Item 4 above	
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of					
corrective actions is ma-	de in accordance with t	he requirements of 10 CF inderstand that no further	R 2.201 (corrective steps	s already taken, co	rrective steps which will be taken, nless specifically requested. Date
LICENSEE'S	1 mileu i				
REPRESENTATIVE			N N A .		
NRC INSPECTOR	R. Rick	Muñoz	KKILI	Mining	07/29/2011
BRANCH CHIEF	HM Var	2/	AM Vans	XII	8/12/2011
NRC FORM 591M PART 1	(Rev. by RIV 3/09)	•	Ī		ORMS\Part1 Publicly Available.doc
Non-Public	Sensitive - S	ecurity-Related	l	Y Dublic	Y Non-Sensitive