NRC FORM 591M PAR' (4-2008) 10 CFR 2.201	Т 1		U.S. NUCLEAR REGULATORY COMMISSION		
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
Arctec Alaska JV 9327 Jerstad Avenue Elmendorf AFB, Alaska 99506 Location: 9327 Jerstad Ave, Elmendorf AFB, Alaska, REPORT NO: 2011-001			U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125		
3. DOCKET NUMBER		4. LICENSE NUMBER		5. DATE OF IN	SPECTION
030-37086		50-29218-01		August 0	2, 2011
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (RRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
Licensee's Statement of Corrective Actions for Item 4, above.					
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date					
LICENSEE'S REPRESENTATIVE			0001		
NRC INSPECTOR	R. Rick M	uñoz	LLIM	him	08/02/2011
BRANCH CHIEF	EN Vasque	2	&M/Jarry		8/12/2011
NRC FORM 591M PART 1					1S\Part1 Publicly Available.doc
Non-Public	Sensitive - Sec	curity-Related	X	Public	X Non-Sensitive