

Davis-BesseNPEm Resource

From: Cooper, Paula
Sent: Tuesday, January 11, 2011 1:47 PM
To: Cooper, Paula
Attachments: [Untitled].pdf

Hearing Identifier: Davis_BesseLicenseRenewal_Saf_NonPublic
Email Number: 857

Mail Envelope Properties (76502014-c7cf-438f-beb0-2a123234617e)

Subject:
Sent Date: 1/11/2011 1:47:19 PM
Received Date: 1/11/2011 1:47:24 PM
From: Cooper, Paula

Created By: Paula.Cooper@nrc.gov

Recipients:
"Cooper, Paula" <Paula.Cooper@nrc.gov>
Tracking Status: None

Post Office: TWMS01.nrc.gov

Files	Size	Date & Time
MESSAGE	2	1/11/2011 1:47:24 PM
[Untitled].pdf	219545	

Options
Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal
Expiration Date:
Recipients Received:

Additional Comment from Joseph DeMare
11/4/10

Transformer fires cause unique pollutants such as dioxin. Since the cause of the 2009 Davis-Besse transformer fire has not been determined, the possibility of another fire must be considered. The EIS must include the ^{impact} of emissions created by transformer fires.

Josh DeMare